

0665	404130	v	214980	nr	v	v	nr	v	v	v	v	v	n	n	n	screen froze. Unable to print audit log called hotline
0666	404140	v	218999	v	nr	v	nr	v	v	v	v	v	n	n	n	
0667	404150	v	203510	v	v	v	v	v	v	v	v	v	n	n	n	problems with the TSX
0668	404210	v	210556	nr	v	nr	v	v	v	v	v	v	n	n	n	
0669	404220	v	207454	v	v	v	v	v	v	v	v	v	n	n	n	
0670	404230	v	207796	v	v	v	v	v	v	v	v	v	n	n	n	
0671	404270	v	217687	v	v	v	v	v	v	v	v	v	n	n	n	
0672	404310	v	221763	v	v	v	v	v	v	v	v	v	n	n	n	
0673	404380	v	212668	v	v	v	v	v	v	v	v	v	n	n	n	
0674	404400	v	216581	v	v	v	v	v	v	v	v	v	n	n	n	
0675	404450	v	215452	v	v	v	v	v	v	v	v	v	n	n	n	
0676	404500	v	211803	v	v	v	v	v	v	v	v	v	n	n	n	red seal was removed in error
0677	404510	v	nr	v	v	v	v	v	v	v	v	v	n	n	n	
0678	404600	v	nr	v	n	v	n	v	v	v	v	v	n	n	n	
0679	402130	v	202877	v	v	v	v	v	v	v	v	v	n	n	n	misunderstanding called the hotline on hold
0680	404800	v	205491	v	v	v	v	v	v	v	v	v	n	n	n	
0681	404900	v	207214	v	v	v	v	v	v	v	v	v	n	n	n	
0682	405100	v	nr	v	v	v	v	v	v	v	v	v	n	n	n	
0683	405160	v	294029	v	v	v	v	v	v	v	v	v	n	n	n	
0684	405180	v	503933	v	v	v	v	v	v	v	v	v	n	n	n	red seal on blue green seal on white copy
0685	405200	v	221465	v	v	v	v	v	v	v	v	v	n	n	n	
0686	405400	v	219813	v	v	v	v	v	v	v	v	v	n	n	n	
0687	405430	v	202116	v	v	v	v	v	v	v	v	v	n	n	n	
0688	405500	v	215412	v	nr	v	nr	v	v	v	v	v	n	n	n	
0689	405600	v	202641	v	v	v	v	v	v	v	v	v	n	n	n	seals attached to the white copy
0690	405610	v	202239	v	v	v	v	v	v	v	v	v	n	n	n	
0691	405700	v	214638	v	v	nr	v	v	v	v	v	v	n	n	n	
0692	405800	v	220053	v	v	v	v	v	v	v	v	v	n	n	n	
0693	405890	v	214646	v	v	v	v	v	v	v	v	v	n	n	n	
0694	405900	v	217261	v	v	v	v	v	v	v	v	v	n	n	n	
0695	406000	v	nr	v	nr	v	nr	v	v	v	v	v	n	n	n	red seal attached to blue green attached to the white copy
0696	406020	v	217914	v	v	v	v	v	v	v	v	v	n	n	n	
0697	406030	v	205850	v	v	v	v	v	v	v	v	v	n	n	n	
0698	406060	v	nr	v	v	v	v	v	v	v	v	v	n	n	n	
0699	406200	v	nr	v	v	v	v	v	v	v	v	v	n	n	n	
0700	406210	v	218221	v	v	v	v	v	v	v	v	v	n	n	n	wait for TSX to start
0701	406210	v	218425	v	v	v	v	v	v	v	v	v	n	n	n	
0702	406280	v	219361	v	v	v	v	v	v	v	v	v	n	n	n	
0703	406300	v	207702	v	v	v	v	v	v	v	v	v	n	n	n	
0704	406310	v	211540	v	v	v	v	v	v	v	v	v	n	n	n	TSX was broken called hotline but cover fixed
0705	406340	v	220285	v	v	v	v	v	v	v	v	v	n	n	n	
0706	406370	v	220800	v	v	v	v	v	v	v	v	v	n	n	n	
0707	406380	v	204099	v	v	v	v	v	v	v	v	v	n	n	n	
0708	406390	v	217116	v	v	v	v	v	v	v	v	v	n	n	n	
0709	406400	v	204507	v	v	v	v	v	v	v	v	v	n	n	n	
0710	406410	v	202400	v	v	v	v	v	v	v	v	v	n	n	n	
0711	406430	v	609860	v	v	v	v	v	v	v	v	v	n	n	n	responses and seals on white copy
0712	406430	v	221679	v	v	v	v	v	v	v	v	v	n	n	n	responses on white copy seals on blue copy
0713	406470	v	209469	v	v	v	v	v	v	v	v	v	n	n	n	
0714	406510	n	nr	v	v	v	v	v	v	v	v	v	n	n	n	error messages
0715	406600	n	202055	v	v	v	v	v	v	v	v	v	n	n	n	red tab lock missing called hotline correct machine
0716	406700	v	206017	v	v	v	v	v	v	v	v	v	n	n	n	technical difficulties needed assistance
0717	406800	v	249723	v	v	v	v	v	v	v	v	v	n	n	n	
0718	406820	v	218683	v	v	v	v	v	v	v	v	v	n	n	n	
0719	407100	v	219553	v	nr	v	v	v	v	v	v	v	n	n	n	
0720	408000	v	203650	v	v	v	v	v	v	v	v	v	n	n	n	
0721	408010	v	207210	v	v	v	v	v	v	v	v	v	n	n	n	
0722	408030	v	201365	v	v	v	v	v	v	v	v	v	n	n	n	
0723	408040	v	205182	v	v	v	v	v	v	v	v	v	n	n	n	
0724	408100	v	220092	v	v	v	v	v	v	v	v	v	n	n	n	
0725	408110	v	223609	v	v	v	v	v	v	v	v	v	n	n	n	
0726	408150	v	229452	v	v	v	v	v	v	v	v	v	n	n	n	
0727	408190	v	nr	v	nr	v	nr	v	v	v	v	v	n	n	n	
0728	408200	v	221157	v	v	v	v	v	v	v	v	v	n	n	n	
0729	408210	v	222776	v	v	v	v	v	v	v	v	v	n	n	n	
0730	408230	v	205558	v	v	v	v	v	v	v	v	v	n	n	n	
0731	408240	v	219708	v	v	v	v	v	v	v	v	v	n	n	n	
0732	408260	v	202144	v	v	v	v	v	v	v	v	v	n	n	n	
0733	408290	v	220050	v	v	v	v	v	v	v	v	v	n	n	n	responses and seals on white copy
0734	408270	v	nr	v	v	v	v	v	v	v	v	v	n	n	n	
0735	408280	v	222877	v	v	v	v	v	v	v	v	v	n	n	n	
0736	408300	v	212527	nr	v	nr	v	v	v	v	v	v	n	n	n	printer problems take up issue with cariszer
0737	408360	v	223599	v	nr	nr	v	v	v	v	v	v	n	n	n	
0738	408390	v	221192	v	v	v	v	v	v	v	v	v	n	n	n	
0739	408400	v	206351	v	v	v	v	v	v	v	v	v	n	n	n	
0740	408440	v	217635	v	v	v	v	v	v	v	v	v	n	n	n	
0741	408490	v	nr	v	v	v	v	v	v	v	v	v	n	n	n	
0742	408500	v	218902	v	v	v	v	v	v	v	v	v	n	n	n	
0743	408550	v	nr	v	v	v	v	v	v	v	v	v	n	n	n	
0744	408560	v	221602	v	v	v	v	v	v	v	v	v	n	n	n	
0745	408570	v	222583	v	v	v	v	v	v	v	v	v	n	n	n	TSX required several re-boots as it kept failing the printer test - it finally passed
0746	408600	v	207461	v	v	v	v	v	v	v	v	v	n	n	n	
0747	408620	v	208221	v	v	v	v	v	v	v	v	v	n	n	n	
0748	408670	v	218725	v	v	v	v	v	v	v	v	v	n	n	n	
0749	408690	v	208948	v	v	v	v	v	v	v	v	v	n	n	n	
0750	408700	v	nr	v	n	nr	nr	v	v	v	v	v	n	n	n	103340
0751	408720	v	249483	v	v	v	v	v	v	v	v	v	n	n	n	
0752	408750	v	215438	v	v	v	v	v	v	v	v	v	n	n	n	
0753	408780	v	212768	v	v	v	v	v	v	v	v	v	n	n	n	
0754	408810	v	202616	v	v	v	v	v	v	v	v	v	n	n	n	printer problems with the cover
0755	408850	v	213231	v	v	v	v	v	v	v	v	v	n	n	n	
0756	408900	v	nr	v	v	v	v	v	v	v	v	v	n	n	n	
0757	408910	v	207931	v	v	v	v	v	v	v	v	v	n	n	n	
0758	409000	v	213503	v	v	v	v	v	v	v	v	v	n	n	n	
0759	409110	v	212606	v	nr	v	v	v	v	v	v	v	n	n	n	
0760	409180	v	nr	v	v	nr	v	v	v	v	v	v	n	n	n	
0761	409190	v	217378	v	v	v	v	v	v	v	v	v	n	n	n	
0762	409210	v	220085	v	v	v	v	v	v	v	v	v	n	n	n	
0763	409240	v	211712	v	v	v	v	v	v	v	v	v	n	n	n	
0764	409280	v	216302	nr	v	v	v	v	v	v	v	v	n	n	n	
0765	409310	v	220471	v	v	v	v	v	v	v	v	v	n	n	n	printer problems not working properly
0766	409420	v	227751	v	v	v	v	v	v	v	v	v	n	n	n	
0767	409440	v	218688	v	v	v	v	v	v	v	v	v	n	n	n	
0768	409460	v	nr	v	v	v	v	v	v	v	v	v	n	n	n	
0769	409490	v	220568	v	v	v	v	v	v	v	v	v	n	n	n	
0770	409500	v	228668	nr	v	v	v	v	v	v	v	v	n	n	n	
0771	409530	v	nr	v	nr	v	nr	v	v	v	v	v	n	n	n	
0772	409600	v	222029	v	v	nr	nr	v	v	v	v	v	n	n	n	
0773	409660	v	208079	v	v	v	v	v	v	v	v	v	n	n	n	
0774	409670	v	208674	v	v	v	v	v	v	v	v	v	n	n	n	printer problems
0775	409690	v	227013	v	v	v	v	v	v	v	v	v	n	n	n	
0776	409780	v	214889	v	v	v	v	v	v	v	v	v	n	n	n	
0777	409800	v	213005	v	v	v	v	v	v	v	v	v	n	n	n	
0778	409810	v	220619	v	v	v	v	v	v	v	v	v	n	n	n	
0779	409880	v	244983	nr	v	v	nr	v	v	v	v	v	n	n	n	
0780	409900	v	215499	v	v	v	v	v	v	v	v	v	n	n	n	
0781	409880	v	217975	v	v											

1500	560000	y	271517	y	y	y	y	y	y	y	y	y	n	n	n	
1501	560140	y	205484	y	y	y	y	y	y	y	y	y	n	n	n	
1502	560150	y	284754	y	y	y	y	y	y	y	y	y	n	n	n	
1503	560200	y	214341	y	y	y	y	y	y	y	y	y	n	n	n	
1504	561510	y	217283	y	y	y	y	n	y	y	y	y	n	n	n	question about total count on TXX open at 715am
1505	561560	y	nr	y	y	y	y	y	y	y	y	y	n	n	n	
1506	562900	y	nr	y	y	y	y	y	y	y	y	y	n	n	n	
1507	562910	y	216347	y	y	y	y	n	y	y	y	y	y	301075	n	called PWH failure to start PSR called authorization line replacing seal
1508	562960	y	207511	y	y	y	y	y	y	y	y	y	n	n	n	
1509	563000	y	202891	y	y	y	y	y	y	y	y	y	n	n	n	
1510	563300	y	212523	y	y	y	y	n	y	y	y	y	n	n	n	did not have access to the fire station (pool site) until 643am
1511	563300	y	nr	y	y	y	y	y	y	y	y	y	n	n	n	
1512	565400	y	504761	y	y	y	y	y	y	y	y	y	n	n	n	
1513	567030	y	202426	y	y	y	y	y	y	y	y	y	n	n	n	
1514	567060	y	205040	y	y	y	y	y	y	y	y	y	n	n	n	
1515	569170	y	217525	y	y	y	y	y	y	y	y	y	n	n	n	
1516	569180	y	217108	nr	y	nr	y	y	y	y	y	y	n	n	n	
1517	571800	y	217519	y	y	y	y	y	y	y	y	y	n	n	n	
1518	573000	y	215436	y	y	y	y	y	y	y	y	y	n	n	n	
1519	573100	y	218030	y	y	y	y	y	y	y	y	y	n	n	n	
1520	574100	y	nr	y	y	y	y	y	y	y	y	y	n	n	n	
1521	575100	y	203966	y	y	y	y	y	y	y	y	y	n	n	n	
1522	575140	y	263401	y	y	y	y	y	y	y	y	y	n	n	n	

Poll Worker Response	Red Tab Lock Match	Green Security Seal Match	Green Tamper Free	Red Security Seal Match	Red Tamper Free	Set Up By 7AM	TSX Signature 2,1,none	Missing seals	
								none	green
YES	1463	1437	1365	1363	1350	1228	1459	1491	1
NO	7	2	21	2	22	208	24	10	1
NO RESPONSE	40	71	124	145	138	74	27	8	10
								both	8
Total returned	1510	1510	1510	1510	1510	1510	1510		1510
Percentage "Yes"	99%	99%	99%	99%	99%	99%	99%		