

Work OrderID	Dept Name	Dept Number	Date Recd	Date Completed	Number of Days to Complete	Number of Hours	Other Costs	Total Cost	Work Done By	Facility	Description of Work	EmployeeID
4	ECPAC	559	6/26/1998	7/13/1998	18	2	10.42	89.7	TS	ECPAC	REPLACE BULB	7
118	ECPAC	559	7/17/1998	8/23/1998	38	1		39.64	RH	ECPAC	OFFICE CHAIR NOT REPAIRABLE	5
153	ECPAC	559	8/31/1998	8/31/1998	1	2		79.28	ML	ECPAC	CLEAN UP PNONE WIRES	4
166	ECPAC	559	7/16/1998	9/1/1998	48	6		237.84	ML	ECPAC	INSTALL PHONES	4
208	ECPAC	559	9/4/1998	9/21/1998	18	4	34.049999	192.61	TS	ECPAC	REPLACE RECEPTACLES	7
398	ECPAC	559	12/14/1998	12/15/1998	2	1		39.64	ML	ECPAC	REMOVE PHONE CORD	4
422	ECPAC	559	11/23/1998	12/1/1998	9	2		79.28	TS	ECPAC	REPAIR TOILET/URINAL	7
423	ECPAC	559	11/23/1998	12/1/1998	9	2		79.28	TS	ECPAC	REPAIR ICE MAKER	7
424	ECPAC	559	11/23/1998	12/1/1998	9	1		39.64	TS	ECPAC	TIGHTEN TOILET SEAT	7
434	ECPAC	559	12/13/1998	12/15/1998	3	10		396.4	ML	ECPAC	REPLACE TOILET SEATS	4
435	ECPAC	559	12/14/1998	12/20/1998	7	2		79.28	ML	ECPAC	REPAIR DOORS	4
436	ECPAC	16410	9/15/1998	1/15/1999	123	8	40	357.12	ML	ECPAC	REPAIR SOAP DISPENSERS	4
463	ECPAC	16410	1/11/1999	1/26/1999	16	6	2.25	240.09	ML BP	ECPAC	REPAIR ELECTRIC OUTLETS	1
464	ECPAC	16410	9/2/1998	1/8/1999	129	7	12.06	289.54	TS	ECPAC	REPLACE WATER FOUNTAIN	7
470	ECPAC	16410	11/23/1998	1/6/1999	45	2	13.2	92.48	TS	ECPAC	REPLACE TILES	7
471	ECPAC	16410	11/23/1998	1/6/1999	45	1		39.64	TS	ECPAC	REPAIR WATER LEAK	7
475	ECPAC	16410	12/9/1998	1/11/1999	34	2		79.28	TS	ECPAC	REPAIR LAMP INSTALL TUBES	7

476	ECPAC	16410	1/22/1999	1/27/1999	6	2		79.28	ML	ECPAC	REPAIR ROPE HOOKS	4
479	ECPAC	45000	2/22/1999	2/25/1999	4	3	30.110001	149.03	ML	ECPAC	INSTALL WINCH	4
528	ECPAC	16410	4/9/1999	4/12/1999	4	1		39.64	ML	ECPAC	ADJUST WATER FOUNTAIN	4
538	ECPAC	16410	2/22/1999	2/25/1999	4	3	30.139999	149.06	ML	ECPAC	INSTALL WINCH	4
545	ECPAC	16410	4/1/1999	4/12/1999	12	1		39.64	ML	ECPAC	TIGHTEN RR SEATS	4
551	ECPAC	16410	2/8/1999	2/10/1999	3	1		39.64	TS	ECPAC	REPLACE TOWEL DISPENSERS	7
637	ECPAC	16410	2/22/1999	3/22/1999	29	2	14.71	93.99	ML	ECPAC	REPAIR SINK FAUCET	4
760	ECPAC	16410	12/4/1998	5/13/1999	161	3		118.92	TS	ECPAC	REPAIR DOORS	7
787	ECPAC	16410	5/3/1999	5/19/1999	17	2	17.790001	97.07	TS	ECPAC	REPLACE BULB	7
788	ECPAC	16410	5/6/1999	5/18/1999	13	3	24.32	143.24	ML	ECPAC	CLEAN DRAIN/REPLACE COVER	4
789	ECPAC	16410	5/5/1999	5/18/1999	14	1		39.64	ML	ECPAC	BOX OFFICE PHONE NOT WKG	4
790	ECPAC	16410	5/7/1999	5/18/1999	12	3		118.92	ML	ECPAC	REPAIR DOOR LOCKS	4
791	ECPAC	16410	4/27/1999	5/18/1999	22	1		39.64	ML	ECPAC	REPAIR NAPKIN DISPOSAL UNIT	4
792	ECPAC	16410	4/13/1999	5/18/1999	36	2	18	97.28	ML	ECPAC	INSTALL NEW VACUUM CORD	4
793	ECPAC	16410	4/16/1999	5/18/1999	33	2		79.28	ML	ECPAC	REPAIRS TO MARQUEE	4
796	ECPAC	16410	5/13/1999	5/13/1999	1	2		79.28	ML TS	ECPAC	REPAIR PIT CONTROLLER	1
813	ECPAC	16410	5/13/1999	5/19/1999	7	4	34.09	192.65	ML	ECPAC	PATCH CONCRETE	4
814	ECPAC	16410	4/13/1999	5/1/1999	19	3		118.92	ML	ECPAC	RUN NEW MODEM LINE	4

817	ECPAC	16410	6/11/1999	6/15/1999	5	1		39.64	ML	ECPAC	INSTALL FIRE ALARM LIGHT	4
825	ECPAC	16410	5/27/1999	6/16/1999	21	3		118.92	TS	ECPAC	MODIFY LIGHT FIXTURE	7
830	ECPAC	16410	4/24/1999	5/5/1999	12	2		79.28	ML	ECPAC	REPAIR TOILET/SEATS	4
834	ECPAC	16410	6/2/1999	6/16/1999	15	2		79.28	TS	ECPAC	MODIFY PIT WINCH	7
843	ECPAC	16410	6/11/1999	6/17/1999	7	2	9.5900002	88.87	TS	ECPAC	REPAIR JAMMED DOOR	7
844	ECPAC	16410	6/11/1999	6/28/1999	18	2		79.28	TS	ECPAC	REPLACE CEILING TILES	7
845	ECPAC	16410	6/11/1999	6/14/1999	4	1		39.64	ML	ECPAC	REPAIR TOILET	4
846	ECPAC	16410	4/29/1999	6/7/1999	40	3	95	213.92	ML	ECPAC	INSTALL NEW DISPENSER	4
847	ECPAC	16410	4/1/1999	6/7/1999	68	1		39.64	ML	ECPAC	REPAIR LIGHT FIXTURE	4
848	ECPAC	16410	4/19/1999	6/7/1999	50	2		79.28	ML	ECPAC	REPAIR DOOR CLOSER	4
850	ECPAC	16410	4/9/1999	6/7/1999	60	1		39.64	ML	ECPAC	REPAIR LIGHT FIXTURE/BULB	4
873	ECPAC	16410	6/2/1999	7/6/1999	35	3	49.57	174.22	TS	ECPAC	CHANGE 5 TUBES	7
875	ECPAC	16410	7/26/1999	7/29/1999	4	1		41.55	ML	ECPAC	CHECK FLUSH PROBLEM	4
935	ECPAC	16410	9/13/1999	9/22/1999	10	1		41.55	RH	ECPAC	REPAIR DOOR	5
964	ECPAC	16410	6/2/1999	8/5/1999	65	2		83.1	TS	ECPC	REPAIR ROOF HATCH	7
993	ECPAC	16410	9/9/1999	9/21/1999	13	1		41.55	RH	ECPAC	CHECK FLUORESCENT LIGHTING	5
998	ECPAC	16410	9/9/1999	9/21/1999	13	3	21.33	145.98	RH	ECPAC	REPLACE OUTLETS	5

1047	ECPAC	16410	9/9/1999	9/14/1999	6	5		207.75	ML	ECPAC	REPAIR LIGHTS/PLAZA OVERHANG	4
1048	ECPAC	16410	9/9/1999	9/16/1999	8	1		41.55	ML	ECPAC	REPLACE PATIO LIGHTS	4
1057	ECPAC	16410	9/8/1999	9/9/1999	2	1		41.55	TS	ECPAC	ADJUST END/CHANGE TUBES	7
1062	ECPAC	16410	8/26/1999	9/8/1999	14	1		41.55	ML	ECPAC	REPAIR TOILET	4
1076	ECPAC	16410	6/11/1999	9/8/1999	90	8	180	512.4	TS	ECPAC	REPLACE DOOR CLOSER	7
1081	ECPAC	16410	8/19/1999	9/2/1999	15	3	37.169998	161.82	ML	ECPAC	REPLACE BALLASTS/TUBES	4
1084	ECPAC	16410	8/19/1999	9/1/1999	14	1		41.55	ML	ECPAC	REBUILD FLUSH VALVE	4
1085	ECPAC	16410	6/28/1999	9/1/1999	66	2	306	389.1	ML	ECPAC	INSTALL DOOR CLOSER	4
1094	ECPAC	16410	8/19/1999	9/2/1999	15	3	11.83	136.48	ML	ECPAC	REPAIR FRAME/INST PLEXIGLASS	4
1101	ECPAC	16410	9/20/1999	9/29/1999	10	2		83.1	RH TS	ECPAC	REPAIR DOOR LOCKS	1
1123	ECPAC	16410	10/11/1999	10/13/1999	3	1		41.55	RH	ECPAC	REPAIR AIR DIFFUSER	5
1126	ECPAC	16410	10/11/1999	10/13/1999	3	1	15.33	56.88	RH	ECPAC	INSTALL A/C SWITCH	5
1127	ECPAC	16410	9/27/1999	10/11/1999	15	7		290.85	AB	ECPAC	REPLACE WARNING STRIPING	6
1132	ECPAC	16410	10/11/1999	10/13/1999	3	1		41.55	RH	ECPAC	CHECK SEAT LIGHT	5
1136	ECPAC	16410	10/11/1999	10/13/1999	3	4		166.2	MB	ECPAC	REINSTALL DOOR	2
1155	ECPAC	16410	10/25/1999	10/28/1999	4	1		41.55	RH	ECPAC	ATTACH SPRINKLER RING	5

1160	ECPAC	16410	10/27/1999	10/27/1999	1	8	31.530001	363.93	ML	ECPAC	INSTALL FUSE/FAN COIL BEARING	4
1167	ECPAC	16410	10/28/1999	11/9/1999	13	1		41.55	RH	ECPAC	REPAIR WINDOW	5
1168	ECPAC	16410	11/15/1999	11/15/1999	1	4	204.73	370.93	RH	ECPAC	INSTALL HOT WATER HEATER	5
1169	ECPAC	16410	11/15/1999	11/18/1999	4	1		41.55	RH	ECPAC	REPAIR FRONT DOORS	5
1170	ECPAC	16410	11/11/1999	11/19/1999	9	2		83.1	AB TS	ECPAC	REPLACE LIGHT COVER	1
1171	ECPAC	16410	11/22/1999	11/23/1999	2	1		41.55	RH	ECPAC	TIGHTEN BANISTER	5
1172	ECPAC	16410	11/22/1999	11/23/1999	2	2		83.1	RH	ECPAC	REPAIR WATER LEAKS/RR	5
1173	ECPAC	16410	10/25/1999	11/1/1999	8	1		41.55	TS	ECPAC	SECURE A/C VENT/RATTLING	7
1212	ECPAC	16410	11/23/1999	12/1/1999	9	1	15	56.55	RH	ECPAC	INSTALL BALLAST	5
1249	ECPAC	16410	12/2/1999	12/8/1999	7	1		41.55	TS	ECPAC	FREE FLUSHING STEM	7
1251	ECPAC	16410	12/17/1999	12/21/1999	5	1		41.55	AB	ECPAC	REPAIR DOOR HANDLE	6
1290	ECPAC	16410	1/28/2000	1/31/2000	4	2		83.1	ML	ECPAC	REPAIR TOILET	4
					TOTALS		\$1,258.22	\$9,176.64				