

WorkOrder ID	Date Entered	Data	Dept Name	Dept Number	Date Recd	Date Started	Date Completed	Num-ber of Days to Com-plete	Number of Hours	Labor Costs	Other Costs	Total Cost	Facility	Gra-fitti	Description of Work	Reques-tor Name	Requestor Phone	Referred To
118			ECPAC	559	7/17/1998		8/23/1998	38	1	0	0	39.64	ECPAC		OFFICE CHAIR NOT REPAIRABLE			
153			ECPAC	559	8/31/1998		8/31/1998	1	2	0	0	79.28	ECPAC		CLEAN UP PNONE WIRES			
166			ECPAC	559	7/16/1998		9/1/1998	48	6	0	0	237.84	ECPAC		INSTALL PHONES			
208			ECPAC	559	9/4/1998		9/21/1998	18	4	0	34.05	192.61	ECPAC		REPLACE RECEPTACLES			
4			ECPAC	559	6/26/1998		7/13/1998	18	2	0	10.42	89.7	ECPAC		REPLACE BULB			
398			ECPAC	559	12/14/1998		12/15/1998	2	1	0	0	39.64	ECPAC		REMOVE PHONE CORD			
422			ECPAC	559	11/23/1998		12/1/1998	9	2	0	0	79.28	ECPAC		REPAIR TOILET/URINAL			
423			ECPAC	559	11/23/1998		12/1/1998	9	2	0	0	79.28	ECPAC		REPAIR ICE MAKER			
424			ECPAC	559	11/23/1998		12/1/1998	9	1	0	0	39.64	ECPAC		TIGHTEN TOILET SEAT			
434			ECPAC	559	12/13/1998		12/15/1998	3	10	0	0	396.4	ECPAC		REPLACE TOILET SEATS			
435			ECPAC	559	12/14/1998		12/20/1998	7	2	0	0	79.28	ECPAC		REPAIR DOORS			
436			ECPAC	16410	9/15/1998		1/15/1999	123	8	0	40	357.12	ECPAC		REPAIR SOAP DISPENSERS			
463			ECPAC	16410	1/11/1999		1/26/1999	16	6	0	2.25	240.09	ECPAC		REPAIR ELECTRIC OUTLETS			
464			ECPAC	16410	9/2/1998		1/8/1999	129	7	0	12.06	289.54	ECPAC		REPLACE WATER FOUNTAIN			
470			ECPAC	16410	11/23/1998		1/6/1999	45	2	0	13.2	92.48	ECPAC		REPLACE TILES			
471			ECPAC	16410	11/23/1998		1/6/1999	45	1	0	0	39.64	ECPAC		REPAIR WATER LEAK			
475			ECPAC	16410	12/9/1998		1/11/1999	34	2	0	0	79.28	ECPAC		REPAIR LAMP INSTALL TUBES			
476			ECPAC	16410	1/22/1999		1/27/1999	6	2	0	0	79.28	ECPAC		REPAIR ROPE HOOKS			
479			ECPAC	45000	2/22/1999		2/25/1999	4	3	0	30.11	149.03	ECPAC		INSTALL WINCH			
528			ECPAC	16410	4/9/1999		4/12/1999	4	1	0	0	39.64	ECPAC		ADJUST WATER FOUNTAIN			
538			ECPAC	16410	2/22/1999		2/25/1999	4	3	0	30.14	149.06	ECPAC		INSTALL WINCH			
545			ECPAC	16410	4/1/1999		4/12/1999	12	1	0	0	39.64	ECPAC		TIGHTEN RR SEATS			
551			ECPAC	16410	2/8/1999		2/10/1999	3	1	0	0	39.64	ECPAC		REPLACE TOWEL DISPENSERS			
637			ECPAC	16410	2/22/1999		3/22/1999	29	2	0	14.71	93.99	ECPAC		REPAIR SINK FAUCET			
760			ECPAC	16410	12/4/1998		5/13/1999	161	3	0	0	118.92	ECPAC		REPAIR DOORS			
787			ECPAC	16410	5/3/1999		5/19/1999	17	2	0	17.79	97.07	ECPAC		REPLACE BULB			
788			ECPAC	16410	5/6/1999		5/18/1999	13	3	0	24.32	143.24	ECPAC		CLEAN DRAIN/REPLACE COVER			
789			ECPAC	16410	5/5/1999		5/18/1999	14	1	0	0	39.64	ECPAC		BOX OFFICE PHONE NOT WKG			
790			ECPAC	16410	5/7/1999		5/18/1999	12	3	0	0	118.92	ECPAC		REPAIR DOOR LOCKS			
791			ECPAC	16410	4/27/1999		5/18/1999	22	1	0	0	39.64	ECPAC		REPAIR NAPKIN DISPOSAL UNIT			
792			ECPAC	16410	4/13/1999		5/18/1999	36	2	0	18	97.28	ECPAC		INSTALL NEW VACUUM CORD			
793			ECPAC	16410	4/16/1999		5/18/1999	33	2	0	0	79.28	ECPAC		REPAIRS TO MARQUEE			
796			ECPAC	16410	5/13/1999		5/13/1999	1	2	0	0	79.28	ECPAC		REPAIR PIT CONTROLLER			
813			ECPAC	16410	5/13/1999		5/19/1999	7	4	0	34.09	192.65	ECPAC		PATCH CONCRETE			
814			ECPAC	16410	4/13/1999		5/1/1999	19	3	0	0	118.92	ECPAC		RUN NEW MODEM LINE			
817			ECPAC	16410	6/11/1999		6/15/1999	5	1	0	0	39.64	ECPAC		INSTALL FIRE ALARM LIGHT			
825			ECPAC	16410	5/27/1999		6/16/1999	21	3	0	0	118.92	ECPAC		MODIFY LIGHT FIXTURE			
830			ECPAC	16410	4/24/1999		5/5/1999	12	2	0	0	79.28	ECPAC		REPAIR TOILET/SEATS			
834			ECPAC	16410	6/2/1999		6/16/1999	15	2	0	0	79.28	ECPAC		MODIFY PIT WINCH			
843			ECPAC	16410	6/11/1999		6/17/1999	7	2	0	9.59	88.87	ECPAC		REPAIR JAMMED DOOR			
844			ECPAC	16410	6/11/1999		6/28/1999	18	2	0	0	79.28	ECPAC		REPLACE CEILING TILES			
845			ECPAC	16410	6/11/1999		6/14/1999	4	1	0	0	39.64	ECPAC		REPAIR TOILET			

846		ECPAC	16410	4/29/1999		6/7/1999	40	3	0	95	213.92	ECPAC		INSTALL NEW DISPENSER			
847		ECPAC	16410	4/1/1999		6/7/1999	68	1	0	0	39.64	ECPAC		REPAIR LIGHT FIXTURE			
848		ECPAC	16410	4/19/1999		6/7/1999	50	2	0	0	79.28	ECPAC		REPAIR DOOR CLOSER			
850		ECPAC	16410	4/9/1999		6/7/1999	60	1	0	0	39.64	ECPAC		REPAIR LIGHT FIXTURE/BULB			
873		ECPAC	16410	6/2/1999		7/6/1999	35	3	0	49.57	174.22	ECPAC		CHANGE 5 TUBES			
875		ECPAC	16410	7/26/1999		7/29/1999	4	1	0	0	41.55	ECPAC		CHECK FLUSH PROBLEM			
935		ECPAC	16410	9/13/1999		9/22/1999	10	1	0	0	41.55	ECPAC		REPAIR DOOR			
964		ECPAC	16410	6/2/1999		8/5/1999	65	2	0	0	83.1	ECPC		REPAIR ROOF HATCH			
993		ECPAC	16410	9/9/1999		9/21/1999	13	1	0	0	41.55	ECPAC		CHECK FLUORESCENT LIGHTING			
998		ECPAC	16410	9/9/1999		9/21/1999	13	3	0	21.33	145.98	ECPAC		REPLACE OUTLETS			
1047		ECPAC	16410	9/9/1999		9/14/1999	6	5	0	0	207.75	ECPAC		REPAIR LIGHTS/PLAZA OVERHANG			
1048		ECPAC	16410	9/9/1999		9/16/1999	8	1	0	0	41.55	ECPAC		REPLACE PATIO LIGHTS			
1057		ECPAC	16410	9/8/1999		9/9/1999	2	1	0	0	41.55	ECPAC		ADJUST END/CHANGE TUBES			
1062		ECPAC	16410	8/26/1999		9/8/1999	14	1	0	0	41.55	ECPAC		REPAIR TOILET			
1076		ECPAC	16410	6/11/1999		9/8/1999	90	8	0	180	512.4	ECPAC		REPLACE DOOR CLOSER			
1081		ECPAC	16410	8/19/1999		9/2/1999	15	3	0	37.17	161.82	ECPAC		REPLACE BALLASTS/TUBES			
1084		ECPAC	16410	8/19/1999		9/1/1999	14	1	0	0	41.55	ECPAC		REBUILD FLUSH VALVE			
1085		ECPAC	16410	6/28/1999		9/1/1999	66	2	0	306	389.1	ECPAC		INSTALL DOOR CLOSER			
1094		ECPAC	16410	8/19/1999		9/2/1999	15	3	0	11.83	136.48	ECPAC		REPAIR FRAME/INST PLEXIGLASS			
1101		ECPAC	16410	9/20/1999		9/29/1999	10	2	0	0	83.1	ECPAC		REPAIR DOOR LOCKS			
1123		ECPAC	16410	10/11/1999		10/13/1999	3	1	0	0	41.55	ECPAC		REPAIR AIR DIFFUSER			
1126		ECPAC	16410	10/11/1999		10/13/1999	3	1	0	15.33	56.88	ECPAC		INSTALL A/C SWITCH			
1127		ECPAC	16410	9/27/1999		10/11/1999	15	7	0	0	290.85	ECPAC		REPLACE WARNING STRIPING			
1132		ECPAC	16410	10/11/1999		10/13/1999	3	1	0	0	41.55	ECPAC		CHECK SEAT LIGHT			
1136		ECPAC	16410	10/11/1999		10/13/1999	3	4	0	0	166.2	ECPAC		REINSTALL DOOR			
1155		ECPAC	16410	10/25/1999		10/28/1999	4	1	0	0	41.55	ECPAC		ATTACH SPRINKLER RING			
1160		ECPAC	16410	10/27/1999		10/27/1999	1	8	0	31.53	363.93	ECPAC		INSTALL FUSE/FAN COIL BEARING			
1167		ECPAC	16410	10/28/1999		11/9/1999	13	1	0	0	41.55	ECPAC		REPAIR WINDOW			
1168		ECPAC	16410	11/15/1999		11/15/1999	1	4	0	204.73	370.93	ECPAC		INSTALL HOT WATER HEATER			
1169		ECPAC	16410	11/15/1999		11/18/1999	4	1	0	0	41.55	ECPAC		REPAIR FRONT DOORS			
1170		ECPAC	16410	11/11/1999		11/19/1999	9	2	0	0	83.1	ECPAC		REPLACE LIGHT COVER			
1171		ECPAC	16410	11/22/1999		11/23/1999	2	1	0	0	41.55	ECPAC		TIGHTEN BANISTER			
1172		ECPAC	16410	11/22/1999		11/23/1999	2	2	0	0	83.1	ECPAC		REPAIR WATER LEAKS/RR			
1173		ECPAC	16410	10/25/1999		11/1/1999	8	1	0	0	41.55	ECPAC		SECURE A/C VENT/RATTLING			
1212		ECPAC	16410	11/23/1999		12/1/1999	9	1	0	15	56.55	ECPAC		INSTALL BALLAST			
1249		ECPAC	16410	12/2/1999		12/8/1999	7	1	0	0	41.55	ECPAC		FREE FLUSHING STEM			
1251		ECPAC	16410	12/17/1999		12/21/1999	5	1	0	0	41.55	ECPAC		REPAIR DOOR HANDLE			
1290		ECPAC	16410	1/28/2000		1/31/2000	4	0	0	0	0	ECPAC		REPAIR TOILET			
1291	5/8/2000	ECPAC	16410	2/23/2000		2/29/2000	7	2	83.09999847	8.8	91.90000153	ECPAC	No	REPLACE TWO ROOF CAPS	JENNIE	0972	BP
1320	5/15/2000	ECPAC	16410	2/24/2000		2/25/2000	2	1	41.54999924	0	41.54999924	ECPAC	No	REPAIR TOILET	ECPAC	0372	BP
1321	5/15/2000	ECPAC	16410	2/24/2000		2/25/2000	2	1	41.54999924	0	41.54999924	ECPAC	No	TIGHTEN HANDRAIL		0372	BP
1341	6/8/2000	ECPAC	16410	2/7/2000		2/8/2000	2	1	41.54999924	0	41.54999924	ECPAC	No	REINSTALL HANDRAIL	MAYES	0372	BP
1343	6/8/2000	ECPAC	16410	2/7/2000		2/8/2000	2	1	41.54999924	0	41.54999924	ECPAC	No	INSTALL BULBS		0372	

1380	6/13/2000	ECPAC	16410	3/29/2000		3/29/2000	1	2	83.09999847	49	132.1000061	ECPAC	No	REPLACE EMERGENCY LIGHT FIXTURE		0372	BP
1428	6/19/2000	ECPAC	16410	3/23/2000		3/27/2000	5	6	249.2999878	0	249.2999878	ECPAC	No	REPAIR HOT WATER HEATERS		0372	BP
1487	6/20/2000	ECPAC	16410	4/17/2000		4/17/2000	1	1	41.54999924	0	41.54999924	ECPAC	No	INSTALL ELECTRIC FIXTURES			
1505	6/20/2000	ECPAC	16410	4/5/2000		4/5/2000	1	3	124.6499939	0	124.6499939	ECPAC	No	REPAIR SINK			
1525	6/20/2000	ECPAC	16410	4/11/2000		4/11/2000	1	4	166.1999969	0	166.1999969	ECPAC	No	RR EXHAUST FAN			
1580	6/21/2000	ECPAC	16410	4/5/2000		4/5/2000	1	1	41.54999924	0	41.54999924	ECPAC	No	REPAIR CHAIR	ECPAC	0372	BP
1582	6/21/2000	ECPAC	16410	4/5/2000		4/5/2000	1	1	41.54999924	0	41.54999924	ECPAC	No	UNCLOGGED DRINKING FOUNTAIN	ECPAC	3372	BP
1585	6/21/2000	ECPAC	16410	3/29/2000		4/5/2000	8	2	83.09999847	140	223.1000061	ECPAC	No	REPLACE FIXTURES	ECPAC	0372	BP
1586	6/21/2000	ECPAC	16410	3/25/2000		4/3/2000	10	3	124.6499939	10	134.6499939	ECPAC	No	REPLACE OUTLETS & COVERS	ECPAC	0372	BP
1591	6/21/2000	ECPAC	16410	3/23/2000		4/6/2000	15	1	41.54999924	0	41.54999924	ECPAC	No	REPLACE WINDOW SEAL	ECPAC	0372	BP
1592	6/21/2000	ECPAC	16410	4/5/2000		4/6/2000	2	1	41.54999924	6	47.54999924	ECPAC	No	REPAIR URINAL	ECPAC	0372	BP
1595	6/21/2000	ECPAC	16410	4/4/2000		4/12/2000	9	1	41.54999924	0	41.54999924	ECPAC	No	REPAIR WHEELCHAIR DOOR	ECPAC	0372	BP
1596	6/21/2000	ECPAC	16410	4/5/2000		4/12/2000	8	1	41.54999924	0	41.54999924	ECPAC	No	CHECK DOOR LOCK	ECPAC	0372	BP
1597	6/21/2000	ECPAC	16410	4/6/2000		4/12/2000	7	1	41.54999924	129.26	170.8099976	ECPAC	No	INSTALL TOWEL DISPENSER	ECPAC	0372	BP
1598	6/21/2000	ECPAC	16410	4/5/2000		4/12/2000	8	6	249.2999878	56.29	305.5899963	ECPAC	No	INSTALL FAN MOTOR	ECPAC	0372	BP
1649	6/22/2000	ECPAC	16410	4/12/2000		4/12/2000	1	2	83.09999847	0	83.09999847	ECPAC	No	REPAIR HANDICAP DOOR LATCHES		0372	BP
1655	8/25/2000	ECPAC	16410	5/16/2000		5/17/2000	2	2	83.09999847	15.5	98.59999847	ECPAC	No	REPLACE HANDLE PART		0372	BP
1656	8/25/2000	ECPAC	16410		5/16/2000	5/16/2000		1	41.54999924	0	41.54999924	ECPAC	No	REPAIR DOOR		0372	BO
1657	8/25/2000	ECPAC	16410	5/17/2000		5/18/2000	2	2	83.09999847	57.65	140.75	ECPAC	No	INSTALL WATER FOUNTAIN VALVES		0372	BP
1658	8/25/2000	ECPAC	16410		5/16/2000	5/16/2000		6	249.2999878	11.22	260.519989	ECPAC	No	PATCH HOLES		0372	BP
1659	8/25/2000	ECPAC	16410	4/24/2000		5/8/2000	15	2	83.09999847	0	83.09999847	ECPAC	No	CHANGE LIGHTS		0372	BP
1660	8/25/2000	ECPAC	16410	5/3/2000		5/4/2000	2	1	41.54999924	0	41.54999924	ECPAC	No	REALIGN DOOR		0372	BP
1661	8/25/2000	ECPAC	16410	5/3/2000		5/4/2000	2	1	41.54999924	0	41.54999924	ECPAC	No	REPLACE LIGHTS		0372	BP
1662	8/25/2000	ECPAC	16410	5/3/2000		5/4/2000	2	1	41.54999924	0	41.54999924	ECPAC	No	INSTALL DIAPHRAGMS IN RR		0372	BP
1724	9/22/2000	ECPAC	16410	5/1/2000		5/1/2000	1	1	41.54999924	0	41.54999924	ECPAC	No	pump at ECPAC			bp
1738	9/25/2000	ECPAC	16410	5/16/2000		5/16/2000	1	2	83.09999847	0	83.09999847	CV	No	BOILERS			BP
1785	9/29/2000	ECPAC	16410	6/8/2000		6/13/2000	6	1	41.54999924	0	41.54999924	ECPAC	No	INSTALL HANDLE KIT		0372	BP
1853	10/2/2000	ECPAC	16410	6/13/2000		6/13/2000	1	2	83.09999847	0	83.09999847	ECPAC	No	PUMP #2			BP
1930	2/1/2001	ECPAC	16410	6/29/2000		7/5/2000	7	1	41.54999924	0	41.54999924	ECPAC	No	HANG BLUEGRASS BANNER		0372	BP
1931	2/1/2001	ECPAC	16410	7/5/2000		7/7/2000	3	1	41.54999924	0	41.54999924	ECPAC	No	REPAIR TOILET		0372	BP
1932	2/1/2001	ECPAC	16410	7/17/2000		7/18/2000	2	1	41.54999924	0	41.54999924	CV	No	REPAIR TOILET		0372	BP
1933	2/1/2001	ECPAC	16410	6/29/2000		7/12/2000	14	1	41.54999924	0	41.54999924	ECPAC	No	REPLACE FLOOD LIGHT		0372	BP
1966	4/17/2001	ECPAC	16410	8/8/2000		8/9/2000	2	2	83.09999847	0	83.09999847	ECPAC	No	REMOVE BANNER		0372	BP
2000	4/17/2001	ECPAC	16410	9/25/2000		9/28/2000	4	1	41.54999924	0	41.54999924	ECPAC	No	INVESTIGATE DAMAGE		0372	P
2008	4/17/2001	ECPAC	16410	9/20/2000		9/25/2000	6	1	29.90999985	0	29.90999985	ECPAC	No	MAKE 6 MAA KEYS		0372	ML
2040	4/17/2001	ECPAC	16410	9/16/2000		9/19/2000	4	4	166.1999969	0	166.1999969	ECPAC	No	CHANGED ALL LIGHTS		0372	BP
2041	4/18/2001	ECPAC	16410	9/18/2000		9/19/2000	2	3	124.6499939	25	149.6499939	ECPAC	No	REPLACE LIGHT TIMER		0372	BP
2042	4/18/2001	ECPAC	16410	9/18/2000		9/19/2000	2	1	41.54999924	0	41.54999924	ECPAC	No	LUBRICATE LATCH		0372	BP
2057	4/18/2001	ECPAC	16410	8/30/2000		9/19/2000	21	4	166.1999969	13.51	179.7099915	ECPAC	No	INSTALL SEATS		0372	BP
2058	4/18/2001	ECPAC	16410	8/30/2000		9/19/2000	21	1	41.54999924	0	41.54999924	ECPAC	No	REPAIR SIDE LIGHTING		0372	BP
2061	4/18/2001	ECPAC	16410	8/7/2000		9/8/2000	33	2	83.09999847	17.69	100.7900009	ECPAC	No	REPAIR CRACK IN CONCRETE		0372	BP
2072	4/18/2001	ECPAC	16410	9/29/2000		10/1/2000	3	1	41.54999924	0	41.54999924	ECPAC	No	INSPECT MAIN DRAPE MOTOR	ED ESTRADA	0343	BP

2073	4/18/2001	ECPAC	16410	9/28/2000		10/4/2000	7	1	41.54999924	0	41.54999924	ECPAC	No	CHECK EMERGENCY GENERATOR		0372	BP
2111	4/19/2001	ECPAC	16410	9/29/2000		10/3/2000	5	2	83.09999847	0	83.09999847	ECPAC	No	REPAIR DOOR LATCH	ED EDSTRADA	0343	BP
2112	4/19/2001	ECPAC	16410	9/26/2000		10/3/2000	8	1	41.54999924	0	41.54999924	ECPAC	No	REPAIR LIGHT UNDER HAND RAIL		0372	BP
2178	4/19/2001	ECPAC	16410	11/24/2000		11/28/2000	5	1	41.54999924	5	46.54999924	ECPAC	No	REPAIR VACUUM CORD		0372	BP
2179	4/19/2001	ECPAC	16410	11/24/2000		11/28/2000	5	4	166.1999969	0	166.1999969	ECPAC	No	REPAIR AISLE LIGHTS		0372	BP
2193	7/11/2001	ECPAC	16410	12/6/2000		12/8/2000	3	1	41.54999924	0	41.54999924	ECPAC	No	Repair light housing.	j. mays	0372	
2199	7/11/2001	ECPAC	16410	12/4/2000		12/6/2000	3	1	41.54999924	0	41.54999924	ECPAC	No	Repair slow drain.	ecpac	0372	
2242	7/18/2001	ECPAC	16410	12/6/2000		12/6/2000	1	1	41.54999924	0	41.54999924	ECPAC	No	Expansion tank			
2301	7/23/2001	ECPAC	16410	12/1/2000		12/1/2000	1	5	207.75	0	207.75	ECPAC	No	Repair per fire inspection.			
2306	7/23/2001	ECPAC	16410	12/5/2000		12/5/2000	1	2	83.09999847	0	83.09999847	ECPAC	No	Patch hole electrical room			
2309	7/23/2001	ECPAC	16410	12/8/2000		12/8/2000	1	1	41.54999924	0	41.54999924	ECPAC	No	Install fire extinguisher-3rd floor			
2310	7/23/2001	ECPAC	16410	12/13/2000		12/13/2000	1	2	83.09999847	0	83.09999847	ECPAC	No	R&R ballast			
2335	7/25/2001	ECPAC	16410	1/2/2001		1/2/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Inventory filters			
2341	7/26/2001	ECPAC	16410	1/9/2001		1/9/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Hang fire extinguishers			
2342	7/26/2001	ECPAC	16410	1/9/2001		1/9/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Remove duct detector			
2376	7/26/2001	ECPAC	16410	1/5/2001		1/5/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Replace 2 ballasts			
2381	7/26/2001	ECPAC	16410	1/26/2001		1/30/2001	5	4	166.1999969	15	181.1999969	ECPAC	No	Repair leakage in Ice Maker machine.	J. Mayes	0372	
2423	7/27/2001	ECPAC	16410	1/24/2001		1/24/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	Prev. Maint.			
2474	7/30/2001	ECPAC	16410	1/18/2001		1/18/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Check operation of AHU #5 & #6.			
2484	7/30/2001	ECPAC	16410	1/24/2001		1/24/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	PM's			
2491	7/30/2001	ECPAC	16410	1/30/2001		1/30/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Repair leaking ice machine			
2517	7/30/2001	ECPAC	16410	1/19/2001		1/19/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	A/C, doors			
2628	7/31/2001	ECPAC	16410	8/18/2000		8/18/2000	1	0.5	20.77499962	0	20.77499962	ECPAC	No	Carpet			
2668	8/1/2001	ECPAC	16410	8/10/2000		8/10/2000	1	1	41.54999924	0	41.54999924	ECPAC	No	Install conduit			
2734	8/2/2001	ECPAC	16410	2/6/2001		2/8/2001	3	2	83.09999847	17	100.0999985	ECPAC	No	Replaced deaphram.			
2824	8/3/2001	ECPAC	16410	2/9/2001		2/9/2001	1	1	53.70999908	101.51	155.2200012	ECPAC		Replaced window.			
2827	8/3/2001	ECPAC	16410	2/12/2001		2/12/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Repaired lock.			
2845	8/3/2001	ECPAC	16410	10/17/2000		10/17/2000	1	2	83.09999847	0	83.09999847	ECPAC	No	Snake drain line			
2846	8/3/2001	ECPAC	16410	10/18/2000		10/18/2000	1	5	207.75	0	207.75	ECPAC	No	Snake 2 drains			
2925	8/6/2001	ECPAC	16410	3/11/2001		3/16/2001	6	2	83.09999847	5	88.09999847	ECPAC	No	Replaced Hinges and Screws			
2926	8/6/2001	ECPAC	16410	3/11/2001		3/16/2001	6	2	83.1000061	25	108.1000061	ECPAC	No	Replaced Toilet Valve Internal Assemblies			
2992	8/7/2001	ECPAC	16410	2/22/2001		2/22/2001	1	3	124.6499939	0	124.6499939	ECPAC	Yes	Sand blast graffiti			
2995	8/7/2001	ECPAC	16410	2/12/2001		2/12/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Broken window			
3013	8/7/2001	ECPAC	16410	2/28/2001		2/28/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Stage cable			
3049	8/7/2001	ECPAC	16410	2/23/2001		2/23/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Rigging			
3114	8/8/2001	ECPAC	16410	11/20/2000		11/20/2000	1	1	41.54999924	0	41.54999924	ECPAC	No	Check time clock			
3149	8/8/2001	ECPAC	16410	11/7/2000		11/7/2000	1	1	41.54999924	0	41.54999924	ECPAC	No	Clear drain			
3154	8/8/2001	ECPAC	16410	11/15/2000		11/15/2000	1	1	41.54999924	0	41.54999924	ECPAC	No	Chiller pump			
3184	8/9/2001	ECPAC	16410	8/29/2000		8/29/2000	1	3	124.6499939	0	124.6499939	ECPAC	No	Move stage lift			
3201	8/10/2001	ECPAC	16410	3/5/2001		3/5/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Rigging			

3212	8/10/2001	ECPAC	16410	3/16/2001	3/16/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Toilet valve.
3216	8/13/2001	ECPAC	16410	3/20/2001	3/20/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Toilet seats.
3226	8/13/2001	ECPAC	16410	3/28/2001	3/28/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Snake snack bar.
3264	8/13/2001	ECPAC	16410	3/22/2001	3/22/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Lighting
3287	8/14/2001	ECPAC	16140	3/22/2001	3/22/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	AH 4-5
3318	8/15/2001	ECPAC	16410	3/13/2001	3/13/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Check back door
3319	8/15/2001	ECPAC	16410	3/13/2001	3/13/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Check toilet
3325	8/15/2001	ECPAC	16410	3/16/2001	3/16/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Repaired loading dock door.
3326	8/15/2001	ECPAC	16410	3/16/2001	3/16/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Replace flushing valve
3337	8/15/2001	ECPAC	16410	3/22/2001	3/22/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Replace two bulbs
3346	8/15/2001	ECPAC	16410	3/28/2001	3/28/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Snaked drain
3408	8/15/2001	ECPAC	16410	2/25/2001	4/3/2001	38	4	166.1999969	80	246.1999969	ECPAC	No	Need caution tape for area not flush
3460	8/16/2001	ECPAC	16410	4/6/2001	4/6/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Snake concession stand
3499	8/16/2001	ECPAC	16410	4/6/2001	4/6/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Snaked floor drain
3527	8/17/2001	ECPAC	16410	4/27/2001	4/27/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Door security
3605	8/17/2001	ECPAC	16410	5/2/2001	5/2/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Snaked sink in concession stand
3618	8/20/2001	ECPAC	16410	5/17/2001	5/17/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Install Fire Exit sign
3639	8/20/2001	ECPAC	16410	5/10/2001	5/10/2001	1	1	41.54999924	0	41.54999924	ECPAC		Check door on women's restroom
3640	8/20/2001	ECPAC	16410	5/14/2001	5/14/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	PMs(1)
3676	8/20/2001	ECPAC	16410	5/1/2001	5/1/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Dressing room lights
3680	8/20/2001	ECPAC	16410	5/4/2001	5/4/2001	1	1	41.54999924	0	41.54999924	ECPAC		Move furniture
3700	8/2/2001	ECPAC	16410	5/3/2001	5/3/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	A.H. #5(1)
3701	8/20/2001	ECPAC	16410	5/4/2001	5/4/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	A.H. #5(2)
3706	8/20/2001	ECPAC	16410	5/8/2001	5/8/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Hang pictures
3707	8/20/2001	ECPAC	16410	5/8/2001	5/8/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Check A.H. #5
3714	8/20/2001	ECPAC	16410	5/11/2001	5/11/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Vent cover
3715	8/20/2001	ECPAC	16410	5/11/2001	5/11/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Door adjust
3718	8/20/2001	ECPAC	16410	5/14/2001	5/14/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	PMs(4)
3738	8/21/2001	ECPAC	16410	5/29/2001	5/29/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	C.F.#2
3740	8/21/2001	ECPAC	16410	5/30/2001	5/30/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Leaky lavatory
3741	8/21/2001	ECPAC	16410	5/30/2001	5/30/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Defective lighting
3743	8/21/2001	ECPAC	16000	5/30/2001	5/30/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	A/C
3758	8/22/2001	ECPAC	16410	5/3/2001	5/3/2001	1	9	373.9499817	0	373.9499817	ECPAC	No	Troubleshoot AH-5 control problem
3761	8/22/2001	ECPAC	16410	5/4/2001	5/4/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	Learned Tracer Summit version
3762	8/22/2001	ECPAC	16410	5/8/2001	5/8/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Hanged painting canvas
3763	8/22/2001	ECPAC	16410	5/8/2001	5/8/2001	1	6	249.2999878	0	249.2999878	ECPAC	No	Troubleshoot AH-5
3771	8/22/2001	ECPAC	16410	5/11/2001	5/11/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Adjusted door
3796	8/22/2001	ECPAC	16410	5/25/2001	5/25/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Checked AH-5 controller problem
3799	8/22/2001	ECPAC	16410	5/29/2001	5/29/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Troubleshoot FC2
3818	8/22/2001	ECPAC	16410	6/6/2001	6/6/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Chiller reset/check
3862	8/22/2001	ECPAC	16410	6/21/2001	6/21/2001	1	0.5	20.77499962	0	20.77499962	ECPAC	No	Bluegrass banner
3924	8/22/2001	ECPAC	16410	6/18/2001	6/18/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Adjusted time clocks
3929	8/22/2001	ECPAC	16410	6/25/2001	6/25/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Hang banner

3930	8/22/2001	ECPAC	16410	6/25/2001		6/25/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Time clocks			
3939	8/22/2001	ECPAC	16410	5/16/2001		5/21/2001	6	1	41.54999924	0	41.54999924	ECPAC	No	Replace light bulb			
3949	8/23/2001	ECPAC	16410	4/27/2001		5/7/2001	11	2	83.09999847	0	83.09999847	ECPAC	No	Repair stalls			
4023	8/23/2001	ECPAC	16410	6/25/2001		6/25/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Hang banner			
4026	8/23/2001	ECPAC	16410	6/27/2001		6/27/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Replace lites/ballast			
4027	8/23/2001	ECPAC	16410	6/27/2001		6/27/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Repair ice machine			
4033	8/23/2001	ECPAC	16410	6/29/2001		6/29/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Check leak			
4050	8/23/2001	ECPAC	16410	6/13/2001		6/13/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	Ceiling tile			
4056	8/23/2001	ECPAC	16410	6/16/2001		6/21/2001	6	1	53.70999908	129.49	183.2000122	ECPAC	No	Call vendor			
4061	8/23/2001	ECPAC	16410	6/16/2001		6/27/2001	12	3	124.6499939	0	124.6499939	ECPAC	No	Trace ice maker leak			
4062	8/23/2001	ECPAC	16410	6/18/2001		6/25/2001	8	2	83.09999847	0	83.09999847	ECPAC	No	Hang bluegrass banner (1)			
4075	8/24/2001	ECPAC	16410	6/16/2001		6/27/2001	12	2	83.09999847	0	83.09999847	ECPAC	No	Replace ballast/bulbs			
4085	8/24/2001	ECPAC	16410	6/3/2001		6/6/2001	4	4	166.1999969	0	166.1999969	ECPAC	No	Patch hole			
4106	8/24/2001	ECPAC	16410	6/3/2001		6/6/2001	4	2	83.09999847	0	83.09999847	W	No	Adjust doors			
4127	8/27/2001	ECPAC	16410	6/16/2001		7/3/2001	18	10	415.5	10	425.5	ECPAC	No	Repair A/C leak			
4157	8/27/2001	ECPAC	16410	6/27/2001		7/16/2001	20	1	41.54999924	0	41.54999924	ECPAC	No	Check out vacuum			
4175	8/27/2001	ECPAC	16410	7/10/2001		7/10/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	Dimmers			
4184	8/27/2001	ECPAC	16410	7/17/2001		7/17/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Repair door			
4185	8/27/2001	ECPAC	16410	7/17/2001		7/17/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	Investigate alarms			
4191	8/27/2001	ECPAC	16410	7/23/2001		7/23/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Door			
4200	8/27/2001	ECPAC	16410	7/2/2001		7/2/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Fan coil leak			
4209	8/27/2001	ECPAC	16410	7/16/2001		7/16/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Remove banner(2)			
4237	8/27/2001	ECPAC	16410	7/10/2001		7/10/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	Theater lighting			
4246	8/27/2001	ECPAC	16410	7/16/2001		7/16/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Remove banner(1)			
4253	8/27/2001	ECPAC	16410	7/3/2001		7/3/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	Insulate/clean drain pan/vacuum cond drain pipe			
4263	8/27/2001	ECPAC	16410	7/9/2001		7/9/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Check Concession stand leak			
4267	8/28/2001	ECPAC	16410	7/11/2001		7/11/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Insulate drain pipe/clean drain pan			
4277	8/28/2001	ECPAC	16410	7/13/2001		7/13/2001	1	5	207.75	0	207.75	ECPAC	No	Replace bearing			
4279	8/28/2001	ECPAC	16410	7/18/2001		7/18/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Install belt guard			
4283	8/28/2001	ECPAC	16410	7/19/2001		7/19/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Chiller problem			
4287	8/28/2001	ECPAC	16410	7/20/2001		7/20/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Chiller operation			
4292	8/28/2001	ECPAC	16410	7/23/2001		7/23/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Chiller plans			
4330	8/31/2001	ECPAC	16410	8/13/2001		8/16/2001	4	2	83.09999847	0	83.09999847	ECPAC	No	Replace outside lights			
4331	8/31/2001	ECPAC	16410	8/16/2001		8/16/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Secure mirrors to walls			
4337	8/31/2001	ECPAC	16410	8/16/2001		8/21/2001	6	3	124.6499939	0	124.6499939	ECPAC	No	Build/install steps			
4416	9/13/2001	ECPAC	16410	8/3/2001		8/3/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Remove from storage			
4451	9/14/2001	ECPAC	16410	8/6/2001		8/6/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Door repair			
4466	9/14/2001	ECPAC	16410	8/20/2001		8/20/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Storage rm. Steps			
4470	9/14/2001	ECPAC	16410	8/21/2001		8/21/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Storage steps			
4605	10/15/2001	ECPAC	16410	8/30/2001		9/5/2001	7	1	41.54999924	0	41.54999924	ECPAC	No	Replace door handle			
4614	10/15/2001	ECPAC	16410	9/18/2001		9/18/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Replace light bulb/check time clocks&lights			
4622	10/15/2001	ECPAC	16410	9/13/2001		9/17/2001	5	1	41.54999924	0	41.54999924	ECPAC	Yes	Remove grafftti(2)			
4623	10/15/2001	ECPAC	16410	9/14/2001		9/14/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Snake drain			
4628	10/15/2001	ECPAC	16410	9/27/2001		9/28/2001	2	1	41.54999924	0	41.54999924	ECPAC	No	Repair toilet			

4630	10/15/2001	ECPAC	16410	9/17/2001		9/25/2001	9	1	41.54999924	0	41.54999924	ECPAC	No	Repair hinges			
4633	10/15/2001	ECPAC	16410	9/17/2001		9/19/2001	3	2	83.09999847	40	123.0999985	ECPAC	No	Rekey lock			
4643	10/15/2001	ECPAC	16410	9/11/2001		9/11/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Tables to ECPAC			
4650	10/15/2001	ECPAC	16410	9/14/2001		9/14/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Drain			
4656	10/16/2001	ECPAC	16410	9/17/2001		9/17/2001	1	1	41.54999924	0	41.54999924	ECPAC	Yes	Remove grafftti(1)			
4660	10/16/2001	ECPAC	16410	9/18/2001		9/18/2001	1	4	166.1999969	0	166.1999969	CH	No	City seals			
4661	10/16/2001	ECPAC	16410	9/19/2001		9/19/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	Air Conditioning			
4669	10/16/2001	ECPAC	16410	9/26/2001		9/26/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Sewer			
4680	10/16/2001	ECPAC	16410	9/11/2001		9/11/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Move tables from CC			
4699	10/16/2001	ECPAC	16410	9/13/2001		9/13/2001	1	4	166.1999969	0	166.1999969	CH	No	Move items to warehouse			
4719	10/17/2001	ECPAC	16410	9/13/2001		9/13/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Move auction items			
4759	10/18/2001	ECPAC	16410	9/19/2001		9/19/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	AH4-5			
4766	11/14/2001	ECPAC	16410	10/15/2001		10/18/2001	4	1	41.54999924	0	41.54999924	ECPAC	No	Repair stall #2 women's rr			
4767	11/14/2001	ECPAC	16410	10/15/2001		10/18/2001	4	1	41.54999924	0	41.54999924	ECPAC	No	Replace doorstop			
4818	11/15/2001	ECPAC	16410	9/27/2001		10/15/2001	19	5	207.75	30	237.75	ECPAC	No	Repair loose stripping			
4826	11/15/2001	ECPAC	16410	9/26/2001		10/2/2001	7	4	166.1999969	45	211.1999969	ECPAC	No	Make plate/replace			
4832	11/15/2001	ECPAC	16410	9/26/2001		10/9/2001	14	34	1412.699951	112.43	1525.130005	ECPAC	No	Install 3 electrical circuits			
4833	11/15/2001	ECPAC	16410	10/6/2001		10/10/2001	5	1	41.54999924	0	41.54999924	ECPAC	No	Attach cove base			
4834	11/15/2001	ECPAC	16410	10/6/2001		10/10/2001	5	1	41.54999924	0	41.54999924	ECPAC	No	Adjust belt tension			
4835	11/15/2001	ECPAC	16410	10/6/2001		10/10/2001	5	2	83.09999847	0	83.09999847	ECPAC	No	Reattach wire mold			
4841	11/16/2001	ECPAC	16410	10/10/2001		10/10/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Air Conditioner			
4850	11/16/2001	ECPAC	16410	10/19/2001		10/19/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Meet electric contractor			
4867	11/19/2001	ECPAC	16410	10/31/2001		10/31/2001	1	4	166.1999969	0	166.1999969	ECPAC	No	Repair doors			
4891	11/19/2001	ECPAC	16410	10/18/2001		10/18/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	A/C program			
4925	11/19/2001	ECPAC	16410	10/1/2001		10/1/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Repair door/check weather strip			
4954	11/26/2001	ECPAC	16410	10/26/2001		10/26/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Check door problem			
4961	11/28/2001	ECPAC	16410	10/31/2001		10/31/2001	1	5	207.75	0	207.75	ECPAC	No	Repair emergency exit door			
4963	11/28/2001	ECPAC	16410	10/31/2001		10/31/2001	0	0	0	0	0	ECPAC	No	Reset time clocks			
4969	11/28/2001	ECPAC	16410	10/5/2001		10/5/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Investigate dedicated circuit installation			
5011	12/12/2001	ECPAC	16410	11/14/2001		12/10/2001	27	9	373.9499817	0	373.9499817	ECPAC	No	Repair locking pin			
5012	12/12/2001	ECPAC	16410	12/8/2001		12/10/2001	3	3	124.6499939	0	124.6499939	ECPAC	No	Pried door open/repair door mortise			
5018	12/18/2001	ECPAC	16410	11/14/2001		11/14/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Tapped hole/replace bolts			
5021	12/19/2001	ECPAC	16410	11/8/2001		11/21/2001	14	2	83.09999847	70	153.1000061	ECPAC	No	Replace paper towel dispenser			
5080	12/19/2001	ECPAC	16410	11/14/2001		11/14/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Tower bolts			
5137	12/26/2001	ECPAC	16410	11/29/2001		11/29/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Boilers			
5142	12/26/2001	ECPAC	16410	11/30/2001		11/30/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Boiler			
5160	12/26/2001	ECPAC	16410	11/28/2001		11/28/2001	1	3	124.6499939	0	124.6499939	ECPAC	No	Repair kiosk			
5184	12/27/2001	ECPAC	16410	11/15/2001		11/15/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Remount conduit box cover			
5217	2/7/2002	ECPAC	16410	12/8/2001		12/11/2001	4	10	415.5	50	465.5	ECPAC	No	Repair winch assembly			
5232	2/8/2002	ECPAC	16410	12/7/2001		12/7/2001	1	7	290.8500061	0	290.8500061	ECPAC	No	PM			
5233	2/8/2002	ECPAC	16410	12/10/2001		12/10/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Stage pin			
5266	2/8/2002	ECPAC	16410	12/12/2001		12/12/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Move 6 tables			
5269	2/8/2002	ECPAC	16410	12/12/2001		12/12/2001	1	2	83.09999847	0	83.09999847	ECPAC	No	Move tables/chairs			
5300	2/8/2002	ECPAC	16410	12/3/2001		12/3/2001	1	1	41.54999924	0	41.54999924	ECPAC	No	Boilers			

5333	3/13/2002	ECPAC	16410	1/12/2002		1/22/2002	11	1	41.54999924	5.2	46.75	ECPAC	No	Install fuses			
5334	3/13/2002	ECPAC	16410	1/17/2002		1/31/2002	15	4	166.1999969	0	166.1999969	ECPAC	No	Secure plexiglass to frame			
5335	3/13/2002	ECPAC	16410	1/12/2002		1/14/2002	3	1	41.54999924	0	41.54999924	ECPAC	No	Turned on breaker			
5336	3/13/2002	ECPAC	16410	1/8/2002		1/25/2002	18	1	41.54999924	0	41.54999924	ECPAC	No	Replace airators			
5337	3/13/2002	ECPAC	16410	1/9/2001		1/25/2002	382	1	41.54999924	0	41.54999924	ECPAC	No	Fastened sign			
5418	3/18/2002	ECPAC	16410	1/10/2002		1/10/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Breaker			
5440	3/18/2002	ECPAC	16410	1/3/2002		1/3/2002	1	4	166.1999969	0	166.1999969	ECPAC	No	A/C controls			
5443	3/18/2002	ECPAC	16410	1/3/2002		1/3/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Boiler			
5444	3/18/2002	ECPAC	16410	1/8/2002		1/8/2002	1	8	332.3999939	0	332.3999939	ECPAC	No	A/C controls(1)			
5445	3/18/2002	ECPAC	16410	1/10/2002		1/10/2002	1	4	166.1999969	0	166.1999969	AC	No	A/C controls(2)			
5452	3/18/2002	ECPAC	16410	1/15/2002		1/15/2002	1	4	166.1999969	0	166.1999969	ECPAC	No	A/C Controls(3)			
5460	3/18/2002	ECPAC	16410	1/29/2002		1/29/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	A/C(1)			
5461	3/18/2002	ECPAC	16410	1/30/2002		1/30/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	A/C (2)			
5488	3/18/2002	ECPAC	16410	1/23/2002		1/23/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Replace light bulbs			
5489	3/18/2002	ECPAC	16410	1/23/2002		1/23/2002	1	5	207.75	0	207.75	ECPAC	No	PMs(2)			
5490	3/18/2002	ECPAC	16410	1/24/2002		1/24/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Replace ballast			
5491	3/18/2002	ECPAC	16410	1/24/2002		1/24/2002	1	8	332.3999939	0	332.3999939	ECPAC	No	PMs(1)			
5492	3/18/2002	ECPAC	16410	1/25/2002		1/25/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Replace fan belt (2)			
5493	3/18/2002	ECPAC	16410	1/25/2002		1/25/2002	1	6	249.2999878	0	249.2999878	ECPAC	No	Remove blower assembly f/concession stand			
5496	3/18/2002	ECPAC	16410	1/30/2002		1/30/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Replace fan belt (1)			
5497	3/18/2002	ECPAC	16410	1/30/2002		1/30/2002	1	3	124.6499939	0	124.6499939	ECPAC	No	Test run FC2			
5499	3/18/2002	ECPAC	16410	1/31/2002		1/31/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	Repair ECPAC markee board			
5503	3/18/2002	ECPAC	16410	1/9/2002		1/9/2002	1	6	249.2999878	0	249.2999878	ECPAC	No	Move tables			
5534	3/29/2002	ECPAC	16410	2/7/2002		2/7/2002	1	4	166.1999969	40	206.1999969	ECPAC	No	Repair door safety mechanism			
5554	4/4/2002	ECPAC	16410	2/8/2002		2/19/2002	12	3	124.6499939	0	124.6499939	ECPAC	No	adjust water regulator/check for leaks			
5564	4/10/2002	ECPAC	16410	2/10/2002		2/19/2002	10	2	83.09999847	33.14	116.2399979	ECPAC	No	Troubleshoot circuit/install switch			
5593	4/17/2002	ECPAC	16410	2/18/2002		2/18/2002	1	3	124.6499939	0	124.6499939	ECPAC	No	Fox portico frame			
5630	4/17/2002	ECPAC	16410	2/15/2002		2/15/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Repair markee			
5644	4/17/2002	ECPAC	16410	2/26/2002		2/26/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Order parts/boiler pump #3			
5700	5/2/2002	ECPAC	16410	3/17/2002		3/28/2002	12	1	41.54999924	7	48.54999924	ECPAC	No	Install screws			
5701	5/2/2002	ECPAC	16410	3/25/2002		3/29/2002	5	5	207.75	0	207.75	ECPAC	No	Reinstall sink/piping			
5702	5/2/2002	ECPAC	16410	3/24/2002		3/25/2002	2	2	83.09999847	24.63	107.7299957	ECPAC	No	Repair lift			
5703	5/2/2002	ECPAC	16410	3/18/2002		3/19/2002	2	1	41.54999924	0	41.54999924	ECPAC	No	Replace light bulbs			
5704	5/2/2002	ECPAC	16410	3/19/2002		3/19/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Repair vacuum			
5705	5/2/2002	ECPAC	16410	3/11/2002		3/12/2002	2	1	41.54999924	0	41.54999924	ECPAC	No	Reset hot water tank			
5757	5/2/2002	ECPAC	16410	3/4/2002		3/4/2002	1	8	332.3999939	0	332.3999939	ECPAC	No	Repair condensate pump			
5758	5/3/2002	ECPAC	16400	3/5/2005		3/5/2002	-1095	6	249.2999878	0	249.2999878	ECPAC		Work on pump #3			
5789	5/8/2002	ECPAC	16410	3/30/2002		3/30/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	Replace outlet cover			
5802	5/16/2002	ECPAC	16410	3/18/2002		3/18/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	Repair backdrop			
5833	5/20/2002	ECPAC	16410	3/1/2002		3/1/2002	1	3	124.6499939	0	124.6499939	ECPAC	No	Assist RotoRooter			
5853	5/20/2002	ECPAC	16410	3/1/2002		3/1/2002	1	4	166.1999969	0	166.1999969	ECPAC	No	RotoRooter			
5937	5/23/2002	ECPAC	16410	4/19/2002		4/19/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	Deliver/set up table			
5938	5/23/2002	ECPAC	16410	4/19/2002		4/19/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Tree lighting power			

5944	5/23/2002	ECPAC	16410	4/4/2002		4/4/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Install cover plate			
5956	5/23/2002	ECPAC	16410	4/24/2002		4/24/2002	1	1	41.54999924	0	41.54999924	CH	No	Pick up/deliver tables			
5961	5/23/2002	ECPAC	16410	4/26/2002		4/26/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	Return tables from ECPAC			
5986	5/24/2002	ECPAC	16410	4/25/2002		4/25/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	Move tables			
6011	5/24/2002	ECPAC	16410	4/16/2002		4/16/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Check power			
6072	5/24/2002	ECPAC	16410	4/25/2002		4/25/2002	1	2	83.09999847	0	83.09999847	CH	No	Move tables(5)			
6073	5/24/2002	ECPAC	16410	4/26/2002		4/26/2002	1	2	83.09999847	0	83.09999847	CH	No	Move tables(6)			
6077	6/10/2002	ECPAC	16410	4/18/2002		5/10/2002	23	1	41.54999924	0	41.54999924	ECPAC	No	Order replacement ice machine			
6078	6/10/2002	ECPAC	16410	4/24/2002		5/13/2002	20	2	83.09999847	306.01	389.1100159	ECPAC	No	Install temp switch			
6079	6/10/2002	ECPAC	16410	5/17/2002		5/22/2002	6	1	41.54999924	0	41.54999924	ECPAC	No	Check upper window			
6080	6/10/2002	ECPAC	16410	5/17/2002		5/22/2002	6	1	41.54999924	0	41.54999924	ECPAC	No	Repaired door as per request			
6081	6/10/2002	ECPAC	16410	5/28/2002		5/31/2002	4	1	41.54999924	0	41.54999924	ECPAC	No	Adjust/lube glass door			
6082	6/10/2002	ECPAC	16410	5/13/2002		5/16/2002	4	3	124.6499939	0	124.6499939	ECPAC	No	Repaired frayed cable			
6137	6/11/2002	ECPAC	16410	5/30/2002		5/30/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Repair child's urinal			
6191	6/18/2002	ECPAC	16410	5/17/2002		5/17/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Windows			
6244	6/19/2002	ECPAC	16410	5/30/2002		5/30/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	Adjust door/lube			
6262	6/19/2002	ECPAC	16410	5/17/2002		5/17/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	Run generator			
6286	7/1/2002	ECPAC	16410	6/16/2002		6/17/2002	2	1	41.54999924	0	41.54999924	ECPAC	No	Repair leak			
6341	7/8/2002	ECPAC	16410	6/11/2002		6/27/2002	17	2	83.09999847	0	83.09999847	ECPAC	No	Replace dispenser			
6342	7/8/2002	ECPAC	16410	6/16/2002		6/27/2002	12	2	83.09999847	0	83.09999847	ECPAC	No	Balance air flow/check motor			
6406	8/30/2002	ECPAC	16410	6/27/2002		6/27/2002	1	6	249.2999878	0	249.2999878	ECPAC	No	PM's(21)			
6449	9/3/2002	ECPAC	16410	6/25/2002		6/25/2002	1	1	41.54999924	0	41.54999924	CH	No	Stage rigging			
6451	9/3/2002	ECPAC	16410	6/26/2002		6/26/2002	1	2	83.09999847	0	83.09999847	CH	No	PM's			
6453	9/3/2002	ECPAC	16410	6/27/2002		6/27/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	PM's(22)			
6459	9/3/2002	ECPAC	16410	6/27/2002		6/28/2002	2	1	41.54999924	0	41.54999924	ECPAC	No	Repair light sockets			
6478	9/5/2002	ECPAC	16410	7/19/2002		7/19/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Repair leak			
6621	9/6/2002	ECPAC	16410	7/16/2002		7/16/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Vendor kiosk			
6626	9/12/2002	ECPAC	16410	8/22/2002		8/23/2002	2	2	83.09999847	0	83.09999847	ECPAC	No	Remove sign			
6627	9/12/2002	ECPAC	16410	8/1/2002		8/9/2002	9	12	498.5999756	15	513.5999756	ECPAC	No	Repair air flow problem			
6635	9/12/2002	ECPAC	16410	8/1/2002		8/7/2002	7	2	83.09999847	0	83.09999847	ECPAC	No	Plunged sinks/clean aerators/ snake on 1 sink			
6747	9/13/2002	ECPAC	16410	8/26/2002		8/26/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Remove donation board			
6810	9/27/2002	ECPAC	16410	9/9/2002		9/10/2002	2	1	41.54999924	0	41.54999924	ECPAC	No	Replace paper towel dispenser			
6811	9/27/2002	ECPAC	16410	9/9/2002		9/10/2002	2	1	41.54999924	0	41.54999924	ECPAC	No	Adjust needle valve			
6812	9/27/2002	ECPAC	16410	9/12/2002		9/16/2002	5	2	83.09999847	0	83.09999847	ECPAC	No	Tightened nuts			
6813	9/27/2002	ECPAC	16410	9/12/2002		9/13/2002	2	3	124.6499939	15	139.6499939	ECPAC	No	Repair/plunge toilet			
6814	9/27/2002	ECPAC	16410	9/11/2002		9/13/2002	3	1	41.54999924	0	41.54999924	ECPAC	No	Repair buffer			
6983	10/21/2002	ECPAC	16410	9/23/2002		10/7/2002	15	2	83.09999847	0	83.09999847	ECPAC	No	Replace soap dispensers			
6984	10/21/2002	ECPAC	16410	8/27/2002		10/9/2002	44	2	83.09999847	21	104.0999985	ECPAC	No	Repair leaky sink			
6985	10/21/2002	ECPAC	16410	10/13/2002		10/16/2002	4	1	41.54999924	0	41.54999924	ECPAC	No	Replace bulb			
6986	10/21/2002	ECPAC	16410	10/14/2002		10/16/2002	3	1	41.54999924	13	54.54999924	ECPAC	No	Replace ballast/bulbs			
6987	10/21/2002	ECPAC	16410	10/16/2002		10/16/2002	1	1	41.54999924	0	41.54999924	ECPAC	No	Repair ice maker			
7025	10/21/2002	ECPAC	16410	10/16/2002		10/17/2002	2	3	124.6499939	0	124.6499939	ECPAC	No	Install lights			
7035	1/17/2003	ECPAC	16410	11/18/2002		11/18/2002	1	1	43.41999817	22	65.41999817	ECPAC	No	Repair toilet			
7107	11/22/2002	ECPAC	16410	10/3/2002		10/3/2002	1	3	124.6499939	0	124.6499939	ECPAC	No	PM's			
7109	11/22/2002	ECPAC	16410	10/4/2002		10/4/2002	1	6	249.2999878	0	249.2999878	ECPAC	No	Continue PM's			
7150	11/22/2002	ECPAC	16410	10/9/2002		10/9/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	Air handler #1 leak			

7164	11/22/2002	ECPAC	16410	10/25/2002		10/25/2002	1	2	83.09999847	0	83.09999847	ECPAC	No	A/C			
7206	1/27/2003	ECPAC	16410	11/12/2002		11/14/2002	3	2	86.83999634	0	86.83999634	ECPAC	No	Remove banner(1)			
7257	1/28/2003	ECPAC	16410	11/18/2002		11/18/2002	1	2	86.83999634	0	86.83999634	ECPAC	No	Setup computer A/C program			
7271	2/24/2003	ECPAC	16410	11/14/2002		11/14/2002	-3652	2	86.83999634	0	86.83999634	ECPAC	No	Remove banner(2)			
7289	2/25/2003	ECPAC	16410	11/14/2002		11/14/2002	1	1	43.41999817	0	43.41999817	ECPAC	No	Remove banner(3)			
7292	2/25/2003	ECPAC	16410	11/14/2002		11/14/2002	1	2	86.83999634	0	86.83999634	ECPAC	No	Unclogged toilet			
7353	2/25/2003	ECPAC	16410	11/25/2002		11/25/2002	1	2	86.83999634	0	86.83999634	ECPAC	No	Season lighting			
7372	3/21/2003	ECPAC	16410	12/10/2002		12/19/2002	10	1	43.41999817	0	43.41999817	ECPAC	No	Replace timer switch			
7373	3/21/2003	ECPAC	16410	10/16/2002		12/12/2002	58	1	43.41999817	0	43.41999817	ECPAC	No	Replace bulbs			
7374	3/21/2003	ECPAC	16410	12/5/2002		12/11/2002	7	1	43.41999817	0	43.41999817	ECPAC	No	Adjust cabinet frame			
7375	3/21/2003	ECPAC	16410	12/5/2002		12/11/2002	7	1	43.41999817	0	43.41999817	ECPAC	No	Install door shields/screws			
7376	3/21/2003	ECPAC	16410	12/18/2002		12/18/2002	1	1	43.41999817	0	43.41999817	ECPAC	No	Adjust door hardware			
7519	3/26/2003	ECPAC	16410	12/11/2002		12/11/2002	1	2	86.83999634	0	86.83999634	ECPAC	No	Repair outlet			
7520	3/26/2003	ECPAC	16410	12/11/2002		12/11/2002	1	7	303.9400024	0	303.9400024	ECPAC	No	Repair chair lift bell			
7521	3/26/2003	ECPAC	16410	12/12/2002		12/12/2002	1	5	217.0999908	0	217.0999908	ECPAC	No	Repair chair lift bell(2)			
7545	4/2/2003	ECPAC	16410	1/22/2003		1/24/2003	3	5	217.0999908	0	217.0999908	ECPAC	No	Replace handle/repair faucet			
7546	4/2/2003	ECPAC	16410	1/23/2003		1/23/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Adjust door closer(1)			
7547	4/2/2003	ECPAC	16410	1/3/2003		1/9/2003	7	1	43.41999817	0	43.41999817	ECPAC	No	Install new lug			
7548	4/2/2003	ECPAC	16410	1/18/2003		1/22/2003	5	2	86.83999634	0	86.83999634	ECPAC	No	Install napkin holders/toilet paper dispenser			
7549	4/2/2003	ECPAC	16410	1/23/2003		1/28/2003	6	5	217.0999908	19.6	236.6999969	ECPAC		Repair defective wiring			
7550	4/2/2003	ECPAC	16410	1/9/2003		1/22/2003	14	1	43.41999817	0	43.41999817	ECPAC	No	Repair carpet vac cord			
7632	4/4/2003	ECPAC	16410	1/14/2003		1/14/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	A/C enclosure door			
7636	4/4/2003	ECPAC	16410	1/15/2003		1/15/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Set up for concert			
7647	4/4/2003	ECPAC	16410	1/23/2003		1/23/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Door			
7648	4/4/2003	ECPAC	16410	1/23/2003		1/23/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Faucet handle			
7649	4/4/2003	ECPAC	16410	1/24/2003		1/24/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Faucet			
7652	4/7/2003	ECPAC	16410	1/24/2003		1/24/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Stagelights			
7653	4/7/2003	ECPAC	16410	1/28/2003		1/28/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Stagelights(1)			
7666	4/7/2003	ECPAC	16410	1/7/2003		1/7/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Repair gate(1)			
7673	4/7/2003	ECPAC	16410	1/9/2003		1/9/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Install wire molding			
7674	4/7/2003	ECPAC	16410	1/9/2003		1/9/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Adjust door closer(2)			
7679	4/7/2003	ECPAC	16410	1/14/2003		1/14/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Repair gate(2)			
7694	4/7/2003	ECPAC	16410	1/30/2003		1/30/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Boilers			
7741	4/9/2003	ECPAC	16410	2/7/2003		2/10/2003	4	2	86.83999634	0	86.83999634	ECPAC	No	Snake drinking fountain drain			
7742	4/9/2003	ECPAC	16410	2/7/2003		2/7/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Snake toilet			
7914	4/21/2003	ECPAC	16410	1/21/2003		3/4/2003	43	8	347.3599854	0	347.3599854	ECPAC	No	Repair circuits to lights			
7915	4/21/2003	ECPAC	16410	3/10/2003		3/14/2003	5	2	86.83999634	1.55	88.38999939	ECPAC	No	Replace cable			
7916	4/21/2003	ECPAC	16410	2/26/2003		3/15/2003	18	1	43.41999817	0	43.41999817	ECPAC	No	Repair faucet			
7917	4/22/2003	ECPAC	16410	2/19/2003		3/26/2003	36	6	260.519989	12.21	272.7299805	ECPAC	No	Rewire lights/new sockets/bulbs			
7918	4/22/2003	ECPAC	16410	3/8/2003		3/26/2003	19	7	303.9400024	0	303.9400024	ECPAC	No	Repair sink leak			
7975	4/23/2003	ECPAC	16410	3/28/2003		3/28/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Repair broken cable under stage			
7986	4/23/2003	ECPAC	16410	3/11/2003		3/11/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Stage rigging			
7987	4/23/2003	ECPAC	16410	3/12/2003		3/12/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Stage rigging(1)			
7991	4/23/2003	ECPAC	16410	3/13/2003		3/13/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Sink			

7994	4/23/2003	ECPAC	16410	3/14/2003		3/14/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Stage pit stabilizer			
8002	4/23/2003	ECPAC	16410	3/18/2003		3/18/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Faucet(1)			
8003	4/23/2003	ECPAC	16410	3/19/2003		3/19/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	Roof clearing			
8005	4/23/2003	ECPAC	16410	3/20/2003		3/20/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Faucet(2)			
8066	5/1/2003	ECPAC	16410	4/3/2003		4/9/2003	7	1	43.41999817	0	43.41999817	ECPAC	No	Repair sink leak			
8067	5/1/2003	ECPAC	16410	4/9/2003		4/10/2003	2	1	43.41999817	0	43.41999817	ECPAC	No	Adjust all doors			
8068	5/1/2003	ECPAC	16410	4/3/2003		4/4/2003	2	3	130.2599945	0	130.2599945	ECPAC	No	Clear drain			
8110	5/5/2003	ECPAC	16410	4/29/2003		4/29/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Reinstalled ceiling vent			
8129	5/9/2003	ECPAC	16410	4/4/2003		4/4/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Drain			
8133	5/9/2003	ECPAC	16410	4/9/2003		4/9/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Sink			
8138	5/9/2003	ECPAC	16410	4/10/2003		4/10/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Door adjust			
8141	5/9/2003	ECPAC	16410	4/11/2003		4/11/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Secure corner cover			
8142	5/9/2003	ECPAC	16410	4/11/2003		4/11/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Adjust drive belt, fix guard			
8162	5/9/2003	ECPAC	16410	4/21/2003		4/21/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Find smoke detector			
8168	5/9/2003	ECPAC	16410	4/2/2003		4/2/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Repair stage cable			
8181	5/9/2003	ECPAC	16410	4/22/2003		4/22/2003	1	6	260.519989	0	260.519989	ECPAC	No	Work on alarm panel			
8238	5/12/2003	ECPAC	16410	4/14/2003		4/14/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Troubleshoot AH #2			
8239	5/12/2003	ECPAC	16410	4/15/2003		4/15/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	Disassemble AH-#2 motor			
8240	5/12/2003	ECPAC	16410	4/16/2003		4/16/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	Reassemble AH-#2 motor			
8241	5/12/2003	ECPAC	16410	4/17/2003		4/17/2003	1	7	303.9400024	0	303.9400024	ECPAC	No	Replace AH #2 motor			
8243	5/12/2003	ECPAC	16410	4/18/2003		4/18/2003	1	5	217.0999908	0	217.0999908	ECPAC	No	Motor replacement AH #2			
8244	5/12/2003	ECPAC	16410	4/22/2003		4/22/2003	1	6	260.519989	0	260.519989	ECPAC	No	Troubleshoot fire alarm			
8245	5/12/2003	ECPAC	16410	4/22/2003		4/22/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Reset time clocks			
8247	5/12/2003	ECPAC	16410	4/22/2003		4/22/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Refuel generator			
8255	5/27/2003	ECPAC	16410	4/29/2003		5/23/2003	25	5	217.0999908	200.2	417.2999878	ECPAC	No	Replace door closer			
8313	6/9/2003	ECPAC	16410	4/29/2003		5/13/2003	15	4	173.6799927	0	173.6799927	ECPAC	No	Replace bolt			
8341	6/9/2003	ECPAC	16410	5/23/2003		5/23/2003	1	6	260.519989	0	260.519989	ECPAC	No	Gates			
8346	6/9/2003	ECPAC	16410	5/28/2003		5/28/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Gates(2)			
8350	6/9/2003	ECPAC	16410	5/30/2003		5/30/2003	1	7	303.9400024	0	303.9400024	ECPAC	No	Gates(1)			
8539	7/23/2003	ECPAC	16410	6/11/2003		6/11/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Time clocks			
11186	12/8/2004	ECPAC	124000	11/1/2004		11/17/2004	17	2	86.83999634	0	86.83999634	ECPAC	No	Repair towel dispenser			
11187	12/8/2004	ECPAC	124000	11/8/2004		11/9/2004	2	1	43.41999817	0	43.41999817	ECPAC	No	Repair door knob			
8375	6/9/2003	ECPAC	16410	5/8/2003		5/8/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Remove door/adjust			
8388	6/10/2003	ECPAC	16410	5/13/2003		5/13/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Adjust door closer			
8408	6/10/2003	ECPAC	16410	5/29/2003		5/29/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Replace water heater wiring			
8488	7/18/2003	ECPAC	16410	6/3/2003		6/3/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Gates			
8490	7/18/2003	ECPAC	16410	6/4/2003		6/4/2003	1	9	390.7799683	0	390.7799683	ECPAC	No	Gates(2)			
8491	7/18/2003	ECPAC	16410	6/5/2003		6/5/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	Gates(3)			
8493	7/18/2003	ECPAC	16410	6/6/2003		6/6/2003	1	9	390.7799683	0	390.7799683	ECPAC	No	Gates(4)			
8494	7/18/2003	ECPAC	16410	6/9/2003		6/9/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	Gates(5)			
8495	7/18/2003	ECPAC	16410	6/10/2003		6/10/2003	1	9	390.7799683	0	390.7799683	ECPAC	No	Gates(6)			
8496	7/18/2003	ECPAC	16410	6/11/2003		6/11/2003	1	9	390.7799683	0	390.7799683	ECPAC	No	Gates(7)			
8498	7/18/2003	ECPAC	16410	6/12/2003		6/12/2003	1	7	303.9400024	0	303.9400024	CH	No	Gates(8)			
8499	7/18/2003	ECPAC	16410	6/13/2003		6/13/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	Gates(9)			
8500	7/18/2003	ECPAC	16410	6/19/2003		6/19/2003	1	5	217.0999908	0	217.0999908	ECPAC	No	Gates(10)			
8509	7/18/2003	ECPAC	16410	6/26/2003		6/26/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Drinking fountain(3rd flr)			
8632	8/19/2003	ECPAC	16410	7/8/2003		7/8/2003	1	9	390.7799683	0	390.7799683	ECPAC	No	Gates(21)			

8633	8/19/2003	ECPAC	16410	7/9/2003	7/9/2003	1	9	390.7799683	0	390.7799683	ECPAC	No	Gates(2)			
8634	8/19/2003	ECPAC	16410	7/10/2003	7/10/2003	1	5	217.0999908	0	217.0999908	ECPAC	No	Gates(3)			
8637	8/19/2003	ECPAC	16410	7/11/2003	7/11/2003	1	5	217.0999908	0	217.0999908	ECPAC	No	Gates(4)			
8640	8/19/2003	ECPAC	16410	7/15/2003	7/15/2003	1	7	303.9400024	0	303.9400024	ECPAC	No	Gates(1)			
8641	8/19/2003	ECPAC	16410	7/16/2003	7/16/2003	1	5	217.0999908	0	217.0999908	ECPAC	No	Gates(5)			
8642	8/19/2003	ECPAC	16410	7/17/2003	7/17/2003	1	5	217.0999908	0	217.0999908	ECPAC	No	Gates(6)			
8643	8/19/2003	ECPAC	16410	7/18/2003	7/18/2003	1	9	390.7799683	0	390.7799683	ECPAC	No	Gates(7)			
8644	8/19/2003	ECPAC	16410	7/21/2003	7/21/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Gates(8)			
8646	8/19/2003	ECPAC	16410	7/22/2003	7/22/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Brick corner			
8647	8/19/2003	ECPAC	16410	7/22/2003	7/22/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Brick corner(2)			
8648	8/19/2003	ECPAC	16410	7/22/2003	7/22/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Clean enclosure			
8649	8/19/2003	ECPAC	16410	7/23/2003	7/23/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Clean enclosure(2)			
8650	8/19/2003	ECPAC	16410	7/23/2003	7/23/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Gates(22)			
8651	8/19/2003	ECPAC	16410	7/24/2003	7/24/2003	1	9	390.7799683	0	390.7799683	ECPAC	No	Gates(9)			
8652	8/19/2003	ECPAC	16410	7/25/2003	7/25/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	Gates(10)			
8653	8/19/2003	ECPAC	16410	7/29/2003	7/29/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Gates(11)			
8677	8/19/2003	ECPAC	16410	7/8/2003	7/8/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Soap dispensers			
8678	8/19/2003	ECPAC	16410	7/17/2003	7/17/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Repair toilet			
8679	8/19/2003	ECPAC	16410	7/16/2003	7/16/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	House wall repair			
8680	8/19/2003	ECPAC	16410	7/24/2003	7/24/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	Dock door wall repair			
8682	8/19/2003	ECPAC	16410	7/29/2003	7/29/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Cleanup pine needles			
8683	8/19/2003	ECPAC	16410	7/31/2003	7/31/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Dressing room A/C			
8718	8/20/2003	ECPAC	16410	7/31/2003	7/31/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Troubleshoot #1 fan cool			
8800	9/26/2003	ECPAC	16410	8/4/2003	8/4/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	PM's			
8801	9/26/2003	ECPAC	16410	8/4/2003	8/4/2003	1	0.5	21.70999908	0	21.70999908	ECPAC	No	Door			
8806	9/26/2003	ECPAC	16410	8/6/2003	8/6/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Return tables to CC			
8843	9/30/2003	ECPAC	16410	8/5/2003	8/5/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Move tables from Community Center			
8861	10/8/2003	ECPAC	16410	8/5/2003	8/5/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Move tables (2)			
8868	8/10/2003	ECPAC	16410	8/5/2003	8/5/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Move tables			
8870	10/8/2003	ECPAC	16410	8/6/2003	8/6/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Move tables(2)			
8873	10/8/2003	ECPAC	16410	8/7/2003	8/7/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Paint hand rail (1)			
8874	10/8/2003	ECPAC	16410	8/8/2003	8/8/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Paint hand rails (2)			
8889	10/8/2003	ECPAC	16410	8/4/2003	8/4/2003	1	5	217.0999908	0	217.0999908	ECPAC	No	A/C controls/pm's			
8912	10/13/2003	ECPAC	16410	9/2/2003	9/8/2003	7	1	43.41999817	0	43.41999817	ECPAC	No	Repair toilet			
8913	10/13/2003	ECPAC	16410	9/2/2003	9/11/2003	10	1	43.41999817	0	43.41999817	ECPAC	No	Check exposed wires			
8973	10/20/2003	ECPAC	16410	9/17/2003	9/17/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Repair air handler #6			
8974	10/20/2003	ECPAC	16410	9/19/2003	9/19/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Repair toilet by back door			
8989	10/21/2003	ECPAC	16410	9/22/2003	9/22/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Install fem. napkin boxes			
9046	10/21/2003	ECPAC	16410	9/29/2003	9/29/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Reset time clock			
9309	12/8/2003	ECPAC	16410	11/12/2003	11/12/2003	1	6	260.519989	0	260.519989	ECPAC	No	Pull cable(1)			
9310	12/8/2003	ECPAC	16410	11/13/2003	11/13/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	Pull cable (2)			
9311	12/8/2003	ECPAC	16410	11/14/2003	11/14/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	Pull cable(3)			
9312	12/8/2003	ECPAC	16410	11/18/2003	11/18/2003	1	8	347.3599854	0	347.3599854	ECPAC	No	Pull cable to sign			
9313	12/8/2003	ECPAC	16410	11/18/2003	11/18/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Stopped up toilet			
9333	12/8/2003	ECPAC	16410	11/19/2003	11/19/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Reset/repair time clocks			
9352	12/8/2003	ECPAC	16410	11/12/2003	11/12/2003	1	9	390.7799683	0	390.7799683	ECPAC	No	Marquee wiring			

9353	12/8/2003	ECPAC	16410	11/13/2003		11/13/2003	1	9	390.7799683	0	390.7799683	ECPAC	No	Marquee wiring(2)			
9354	12/8/2003	ECPAC	16410	11/14/2003		11/14/2003	1	9	390.7799683	0	390.7799683	ECPAC	No	Marquee wiring(3)			
9355	12/8/2003	ECPAC	16410	11/18/2003		11/18/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Marquee wiring(4)			
9389	1/12/2004	ECPAC	16410	12/10/2003		12/10/2003	1	3	130.2599945	15	145.2599945	ECPAC	No	Replace ballast(1)			
9390	1/12/2004	ECPAC	16410	12/10/2003		12/10/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Replace handle springs			
9391	1/12/2004	ECPAC	16410	11/19/2003		12/1/2003	13	1	43.41999817	0	43.41999817	ECPAC	No	Adjust door closer			
9438	1/14/2004	ECPAC	16410	12/3/2003		12/3/2003	1	1	43.41999817	0	43.41999817	ECPAC	No	Clean up tower enclosure			
9449	1/14/2004	ECPAC	16410	12/22/2003		12/22/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Clear drain			
9462	1/14/2004	ECPAC	16410	12/2/2003		12/2/2003	1	7	303.9400024	0	303.9400024	ECPAC	No	Sign(1)			
9463	1/14/2003	ECPAC	16410	12/2/2003		12/2/2003	1	1	43.41999817	0	43.41999817	CH	No	PM's			
9464	1/14/2004	ECPAC	16410	12/3/2003		12/3/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Sign(2)			
9467	1/14/2004	ECPAC	16410	12/4/2003		12/4/2003	1	4	173.6799927	0	173.6799927	ECPAC	No	Sign(9)			
9476	1/14/2004	ECPAC	16410	12/9/2003		12/9/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Stage anchor			
9489	1/14/2004	ECPAC	16410	12/18/2003		12/18/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Marquee switch			
9491	1/14/2004	ECPAC	16410	12/18/2003		12/18/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Toilet repair			
9501	1/14/2004	ECPAC	16410	12/3/2003		12/3/2003	1	2	86.83999634	0	86.83999634	ECPAC	No	Clean enclosure			
9528	1/15/2004	ECPAC	16410	12/10/2003		12/10/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Replace ballast(2)			
9559	1/15/2004	ECPAC	16410	12/22/2003		12/22/2003	1	3	130.2599945	0	130.2599945	ECPAC	No	Snake drain			
9573	2/9/2004	ECPAC	16410	1/18/2004		1/23/2004	6	8	347.3599854	15	362.3599854	ECPAC	No	Prime/paint stair steps			
9576	2/9/2004	ECPAC	16410	1/18/2004		1/22/2004	5	3	130.2599945	5	135.2599945	ECPAC	No	Adjust door closer/replace door stop			
9759	3/16/2004	ECPAC	16410	2/3/2004		2/3/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Change filters Control Rm			
9762	3/16/2004	ECPAC	16410	2/24/2004		2/24/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Roof drains			
9765	3/16/2004	ECPAC	16410	2/2/2004		2/2/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Lights			
9775	3/16/2004	ECPAC	16410	2/18/2004		2/18/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Install diaphragm			
9809	3/17/2004	ECPAC	16410	2/4/2004		2/4/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Time clocks			
9931	4/19/2004	ECPAC	16410	3/17/2004		3/17/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Repair door/door opener			
9964	4/23/2004	ECPAC	16410	3/26/2004		3/26/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Rest room faucets			
9979	4/23/2004	ECPAC	16410	3/3/2004		3/3/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Retrieve snake/roof drain			
9983	4/23/2004	ECPAC	16410	3/11/2004		3/11/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Repair all sinks			
9997	4/23/2004	ECPAC	16410	3/3/2004		3/3/2004	1	8	347.3599854	0	347.3599854	ECPAC	No	Hot water pump seal(1)			
10000	4/23/2004	ECPAC	16410	3/4/2004		3/4/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Hot water pump seal(2)			
10002	4/23/2004	ECPAC	16410	3/5/2004		3/5/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Hot water pump seal(3)			
10003	4/23/2004	ECPAC	16410	3/11/2004		3/11/2004	1	7	303.9400024	0	303.9400024	ECPAC	No	Hot water pump seal(5)			
10009	4/26/2004	ECPAC	16410	3/17/2004		3/17/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Stage & Lobby door			
10022	4/26/2004	ECPAC	16410	3/4/2004		3/4/2004	1	8	347.3599854	0	347.3599854	ECPAC	No	Repair boiler pump			
10045	4/26/2004	ECPAC	16410	3/30/2004		3/30/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Check front door			
10046	4/26/2004	ECPAC	16410	3/30/2004		3/30/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Remove faucet assembly			
10070	4/27/2004	ECPAC	16410	3/30/2004		3/30/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Door			
10148	5/24/2004	ECPAC	16410	4/26/2004		4/26/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Women's RR faucet			
10149	5/24/2004	ECPAC	16410	4/26/2004		4/26/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Dressing room toilet			
10167	5/24/2004	ECPAC	16410	4/15/2004		4/15/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Remove banner			
10177	5/24/2004	ECPAC	16410	4/1/2004		4/1/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Door handle			
10204	5/24/2004	ECPAC	16410	4/1/2004		4/1/2004	1	9	390.7799683	0	390.7799683	ECPAC	No	Repair sink/remount			
10205	5/24/2004	ECPAC	16410	4/2/2004		4/2/2004	1	6	260.519989	0	260.519989	ECPAC	No	Repair/mount faucet assembly			
10206	5/24/2004	ECPAC	16410	4/2/2004		4/2/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Replace plexiglass			
10210	5/24/2004	ECPAC	16410	4/13/2004		4/13/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Hang banner			

10230	6/16/2004	ECPAC	16410	5/14/2004		5/20/2004	7	2	86.83999634	2.88	89.71999359	ECPAC	No	Repair rail			
10231	6/16/2004	ECPAC	16410	5/2/2004		5/12/2004	11	8	347.3599854	125	472.3599854	ECPAC	No	Replace mortice/re-pin lock cylinder			
10284	6/18/2004	ECPAC	16410	5/3/2004		5/3/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Stage door			
10343	6/22/2004	ECPAC	16410	5/26/2004		5/26/2004	1	8	347.3599854	0	347.3599854	ECPAC	No	PM's			
10344	6/22/2004	ECPAC	16410	5/27/2004		5/27/2004	1	5	217.0999908	0	217.0999908	ECPAC	No	Continue PM's			
10353	6/22/2004	ECPAC	16410	5/5/2004		5/5/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Door lock			
10378	7/29/2004	ECPAC	16410	5/6/2004		6/7/2004	33	6	260.519989	0	260.519989	ECPAC	No	Replace hydraulic closer			
10379	7/29/2004	ECPAC	16410	6/13/2004		6/22/2004	10	8	347.3599854	0	347.3599854	ECPAC	No	Repair electrical			
10380	7/29/2004	ECPAC	16410	6/25/2004		6/28/2004	4	2	86.83999634	12.28	99.11999512	ECPAC	No	Repair track lights			
10381	7/29/2004	ECPAC	16410	6/25/2004		6/28/2004	4	2	86.83999634	55.15	141.9899902	ECPAC	No	Change out timers			
10382	7/29/2004	ECPAC	16410	6/10/2004		6/17/2004	8	1	43.41999817	0	43.41999817	ECPAC	No	Check noise in air handler			
10463	7/30/2004	ECPAC	16410	6/22/2004		6/22/2004	1	8	347.3599854	0	347.3599854	ECPAC	No	Repair lighting			
10503	8/2/2004	ECPAC	16410	6/4/2004		6/4/2004	1	6	260.519989	0	260.519989	ECPAC	No	Doors			
10506	8/2/2004	ECPAC	16410	6/7/2004		6/7/2004	1	7	303.9400024	0	303.9400024	ECPAC	No	Doors(2)			
10523	8/3/2004	ECPAC	16410	6/14/2004		6/14/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Noise in storage area			
10557	8/11/2004	ECPAC	124000	7/27/2004		7/28/2004	2	1	43.41999817	0	43.41999817	ECPAC	No	Adjust/lube door			
10558	8/11/2004	ECPAC	124000	7/27/2004		7/28/2004	2	1	43.41999817	0	43.41999817	ECPAC	No	Check A/C			
10563	8/11/2004	ECPAC	124000	7/27/2004		7/29/2004	3	1	43.41999817	0	43.41999817	ECPAC		Replace plexiglass			
10644	9/9/2004	ECPAC	124000	7/27/2004		7/27/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Star paint			
10669	9/23/2004	ECPAC	124000	7/22/2004		7/22/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Concrete repair/main entrance			
10670	9/23/2004	ECPAC	124000	7/23/2004		7/23/2004	1	6	260.519989	0	260.519989	ECPAC	No	Continue concrete patch			
10679	9/23/2004	ECPAC	124000	7/8/2004		7/8/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Telephones(1)			
10680	9/23/2004	ECPAC	124000	7/9/2004		7/9/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Telephones(2)			
10681	9/23/2004	ECPAC	124000	7/12/2004		7/12/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Telephones(3)			
10682	9/23/2004	ECPAC	124000	7/13/2004		7/13/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Telephones(4)			
10683	9/23/2004	ECPAC	124000	7/14/2004		7/14/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Telephones(5)			
10690	9/23/2004	ECPAC	124000	7/26/2004		7/26/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Telephones			
10691	9/23/2004	ECPAC	124000	7/27/2004		7/27/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Repair toilet			
10704	10/8/2004	ECPAC	124000	8/18/2004		8/18/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Replace outlet			
10705	10/8/2004	ECPAC	124000	7/23/2004		8/2/2004	11	2	86.83999634	0	86.83999634	ECPAC	No	Install telephone cover panel			
10757	10/8/2004	ECPAC	124000	8/31/2004		8/31/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Repair front door			
10765	10/11/2004	ECPAC	124000	8/4/2004		8/4/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Fixtures(1)			
10766	10/11/2004	ECPAC	124000	8/5/2004		8/5/2004	1	8	347.3599854	0	347.3599854	ECPAC	No	Fixtures(2)			
10767	10/11/2004	ECPAC	124000	8/6/2004		8/6/2004	1	8	347.3599854	0	347.3599854	ECPAC	No	Fixtures(3)			
10768	10/11/2004	ECPAC	124000	8/10/2004		8/10/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Caulking fixtures			
10782	10/11/2004	ECPAC	124000	8/18/2004		8/18/2004	1	8	347.3599854	0	347.3599854	ECPAC	No	Faucets			
10784	10/11/2004	ECPAC	124000	8/26/2004		8/26/2004	1	8	347.3599854	0	347.3599854	ECPAC	No	Faucets(1)			
10785	10/11/2004	ECPAC	124000	8/27/2004		8/27/2004	1	8	347.3599854	0	347.3599854	ECPAC		Faucets(2)			
10786	10/11/2004	ECPAC	124000	8/30/2004		8/30/2004	1	8	347.3599854	0	347.3599854	ECPAC	No	Diaper table			
10787	10/11/2004	ECPAC	124000	8/31/2004		8/31/2004	1	6	260.519989	0	260.519989	ECPAC	No	Soap dispenser			
10793	10/11/2004	ECPAC	124000	8/5/2004		8/5/2004	1	9	390.7799683	0	390.7799683	ECPAC	No	Plumbing(1)			
10794	10/11/2004	ECPAC	124000	8/6/2004		8/6/2004	1	8	347.3599854	0	347.3599854	ECPAC	No	Plumbing(2)			
10804	10/11/2004	ECPAC	124000	8/18/2004		8/18/2004	1	8	347.3599854	0	347.3599854	ECPAC	No	Plumbing(3)			
10805	10/11/2004	ECPAC	124000	8/19/2004		8/19/2004	1	5	217.0999908	0	217.0999908	ECPAC	No	Plumbing(4)			
10818	10/11/2004	ECPAC	124000	8/12/2004		8/12/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Clean light fixtures			
10819	10/11/2004	ECPAC	124000	8/12/2004		8/12/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Clean roof			

10830	10/12/2004	ECPAC	124000	8/27/2004		8/27/2004	1	9	390.7799683	0	390.7799683	ECPAC	No	Repair A/C(1)			
10831	10/12/2004	ECPAC	124000	8/30/2004		8/30/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Check air handling unit			
10832	10/12/2004	ECPAC	124000	8/31/2004		8/31/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Check air handling unit #2 & \$6			
10845	10/12/2004	ECPAC	124000	8/22/2004		8/22/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Install outlet			
10847	10/14/2004	ECPAC	124000	8/27/2004		9/1/2004	6	1	43.41999817	0	43.41999817	ECPAC	No	Check stairs for trip hazard			
10848	10/14/2004	ECPAC	124000	9/1/2004		9/1/2004	1	1	43.41999817	0	43.41999817	ECPAC	Yes	Remove graffiti			
10849	10/14/2004	ECPAC	124000	9/16/2004		9/29/2004	14	5	217.0999908	13.62	230.719986	ECPAC	No	Clean vacuum			
10889	10/15/2004	ECPAC	124000	9/2/2004		9/2/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Sink caulking			
10890	10/15/2004	ECPAC	124000	9/2/2004		9/2/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Entry star paint			
10891	10/15/2004	ECPAC	124000	9/2/2004		9/2/2004	1	5	217.0999908	0	217.0999908	ECPAC	No	Sinks			
10892	10/15/2004	ECPAC	124000	9/3/2004		9/3/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Entry star paint(2)			
10900	10/15/2004	ECPAC	124000	9/8/2004		9/8/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Sinks(2)			
10905	10/15/2004	ECPAC	124000	9/9/2004		9/9/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Refurbish vacuum cleaner			
10925	10/15/2004	ECPAC	124000	9/24/2004		9/24/2004	1	5	217.0999908	0	217.0999908	ECPAC	No	Vacuum Cleaner			
10948	10/15/2004	ECPAC	124000	9/23/2004		9/23/2004	1	6	260.519989	0	260.519989	ECPAC	No	PM's			
10954	10/15/2004	ECPAC	124000	9/2/2004		9/2/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Attach fire alarm wire molding			
10979	10/18/2004	ECPAC	124000	9/7/2004		9/7/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Lights			
11000	10/18/2004	ECPAC	124000	9/29/2004		9/29/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Electrical			
11008	11/2/2004	ECPAC	124000	10/7/2004		10/14/2004	8	2	86.83999634	0	86.83999634	ECPAC	No	Covered hole			
11071	11/5/2004	ECPAC	124000	10/6/2004		10/6/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Roof tar			
11072	11/5/2004	ECPAC	124000	10/7/2004		10/7/2004	1	5	217.0999908	0	217.0999908	ECPAC	No	Roof tar			
11073	11/5/2004	ECPAC	124000	10/7/2004		10/7/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Stair tread			
11075	11/5/2004	ECPAC	124000	10/8/2004		10/8/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Wall damage			
11097	11/5/2004	ECPAC	124000	10/29/2004		10/29/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Air handling problem			
11098	11/5/2004	ECPAC	124000	10/29/2004		10/29/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Roof leak			
11099	11/5/2004	ECPAC	124000	10/29/2004		10/29/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Time clocks			
11101	11/8/2004	ECPAC	124000	10/5/2004		10/5/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Reset time clocks			
11106	11/8/2004	ECPAC	124000	10/21/2004		10/21/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Hang picture			
11170	11/8/2004	ECPAC	124000	10/13/2004		10/13/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Label fire extinguishers			
11180	11/8/2004	ECPAC	124000	10/27/2004		10/27/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Clear roof drain			
11269	12/10/2004	ECPAC	124000	11/3/2004		11/3/2004	1	4	173.6799927	0	173.6799927	ECPAC	No	Stage bar			
11336	2/14/2005	ECPAC	124000	12/1/2004		12/8/2004	8	1	43.41999817	0	43.41999817	ECPAC	No	Need phone cord for 3-line phone			
11386	2/17/2005	ECPAC	124000	1/12/2005		1/12/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Repair leak			
11387	2/16/2005	ECPAC	124000	1/18/2005		1/27/2005	10	5	217.0999908	0	217.0999908	ECPAC	No	Rewire sockets/replace bulbs			
11388	2/17/2005	ECPAC	124000	12/21/2004		1/10/2005	21	3	130.2599945	0	130.2599945	ECPAC	No	Look for lock or rebuy disp			
11389	2/17/2005	ECPAC	124000	12/16/2004		1/10/2005	26	16	694.7199707	0	694.7199707	ECPAC	No	Repair drywall/paint/install doorstop			
11390	2/17/2005	ECPAC	124000	12/21/2004		1/11/2005	22	3	130.2599945	0	130.2599945	ECPAC	No	Reinstall paper towel holder/repair lock			
11466	2/17/2005	ECPAC	124000	12/9/2004		12/9/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Clear drain			
11495	3/17/2005	ECPAC	124000	12/6/2004		12/6/2004	1	0.5	21.70999908	0	21.70999908	ECPAC	No	Stage rigging			
11518	3/17/2005	ECPAC	124000	12/3/2004		12/3/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Replace dryer receptacle/power cord			
11522	3/17/2005	ECPAC	124000	12/8/2004		12/8/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Check door/door handle			
11527	3/17/2005	ECPAC	124000	12/9/2004		12/9/2004	1	1	43.41999817	0	43.41999817	ECPAC	No	Repair dressing room door handle			

11529	3/17/2005	ECPAC	124000	12/9/2004		12/9/2004	1	3	130.2599945	0	130.2599945	ECPAC	No	Replace outside light bulbs			
11531	3/17/2005	ECPAC	124000	12/14/2004		12/14/2004	1	2	86.83999634	0	86.83999634	ECPAC	No	Unclog 2 toilets			
11594	3/21/2005	ECPAC	124000	1/3/2005		1/3/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Shower			
11596	3/21/2005	ECPAC	124000	1/3/2005		1/3/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Block			
11601	3/21/2005	ECPAC	124000	1/6/2005		1/6/2005	1	7	303.9400024	0	303.9400024	ECPAC	No	PM's			
11620	3/21/2005	ECPAC	124000	1/5/2005		1/5/2005	1	4	173.6799927	0	173.6799927	ECPAC	Yes	Remove graffiti			
11631	4/22/2005	ECPAC	124000	1/12/2005		2/3/2005	23	36	1563.119873	80	1643.119873	ECPAC	No	Repair leak			
11632	4/22/2005	ECPAC	124000	2/15/2005		2/23/2005	9	3	130.2599945	0	130.2599945	ECPAC	No	Repair toilet			
11633	4/22/2005	ECPAC	124000	2/12/2005		2/23/2005	12	3	130.2599945	0	130.2599945	ECPAC	No	Snake toilets			
11634	4/22/2005	ECPAC	124000	2/12/2005		2/15/2005	4	0.5	21.70999908	0	21.70999908	ECPAC	No	Repair lights			
11635	4/22/2005	ECPAC	124000	2/12/2005		2/15/2005	4	0.5	21.70999908	0	21.70999908	ECPAC	No	Repair lights			
11701	4/25/2005	ECPAC	124000	2/2/2005		2/2/2005	1	3	130.2599945	0	130.2599945	ECPAC	No	Sump pump			
11703	4/25/2005	ECPAC	124000	2/2/2005		2/2/2005	1	4	173.6799927	0	173.6799927	ECPAC	No	Sound system			
11704	4/25/2005	ECPAC	124000	2/3/2005		2/3/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Sound system			
11705	4/25/2005	ECPAC	124000	2/3/2005		2/3/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Sump pump			
11706	4/25/2005	ECPAC	124000	2/3/2005		2/3/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Repair roof leak			
11709	4/25/2005	ECPAC	124000	2/4/2005		2/4/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Sump pump			
11713	4/25/2005	ECPAC	124000	2/15/2005		2/15/2005	1	3	130.2599945	0	130.2599945	ECPAC	No	Plumbing			
11762	4/27/2005	ECPAC	124000	2/15/2005		2/15/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Light contactor			
11783	4/27/2005	ECPAC	124000	2/15/2005		2/15/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Repair contactor/strg rm			
11793	4/27/2005	ECPAC	124000	2/3/2005		2/7/2005	5	18	781.5599365	0	781.5599365	ECPAC	No	Repair sky hatch			
11795	4/27/2005	ECPAC	124000	2/8/2005		2/8/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Repair slow toilet			
11799	5/6/2005	ECPAC	124000	3/19/2005		3/19/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Fasten mirror			
11839	5/9/2005	ECPAC	124000	3/23/2005		3/23/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Close moon roof			
11840	5/9/2005	ECPAC	124000	3/24/2005		3/24/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Close moon roof			
11863	5/9/2005	ECPAC	124000	3/22/2005		3/22/2005	1	4	173.6799927	0	173.6799927	ECPAC	No	Drain			
11864	5/9/2005	ECPAC	124000	3/23/2005		3/23/2005	1	9	390.7799683	0	390.7799683	ECPAC	No	Drain			
11865	5/9/2005	ECPAC	124000	3/24/2005		3/24/2005	1	3	130.2599945	0	130.2599945	ECPAC	No	Drain			
11914	5/10/2005	ECPAC	124000	3/18/2005		3/18/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Fire alarm system			
11917	5/10/2005	ECPAC	124000	3/22/2005		3/22/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Plugged drain			
11954	5/16/2005	ECPAC	124000	4/19/2005		4/20/2005	2	3	130.2599945	0	130.2599945	ECPAC	No	Replace urinal kit			
11955	5/16/2005	ECPAC	124000	3/20/2005		4/1/2005	13	1	43.41999817	0	43.41999817	ECPAC	No	Adjust closer			
11956	5/16/2005	ECPAC	124000	3/20/2005		4/7/2005	19	10	434.1999817	0	434.1999817	ECPAC	No	Snake sewer line			
12071	5/18/2005	ECPAC	124000	4/11/2005		4/11/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Chiller pump			
12104	5/18/2005	ECPAC	124000	4/12/2005		4/12/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Boiler pump			
12143	6/24/2005	ECPAC	124000	4/19/2005		5/3/2005	15	2	86.83999634	0	86.83999634	ECPAC	No	Replace seats			
12144	6/24/2005	ECPAC	124000	4/25/2005		5/3/2005	9	2	86.83999634	0	86.83999634	ECPAC	No	Attach towel dispenser			
12145	6/24/2005	ECPAC	124000	4/25/2005		5/3/2005	9	3	130.2599945	0	130.2599945	ECPAC	No	Repair door handle			
12146	6/24/2005	ECPAC	124000	4/25/2005		5/3/2005	9	2	86.83999634	0	86.83999634	ECPAC	No	Repair door handle			
12147	6/24/2005	ECPAC	124000	4/22/2005		5/17/2005	26	4	173.6799927	0	173.6799927	ECPAC	No	Replace paper towel dispenser			
12235	6/29/2005	ECPAC	124000	5/16/2005		5/16/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Telephone line			
12240	6/29/2005	ECPAC	124000	5/19/2005		5/19/2005	1	6	260.519989	0	260.519989	ECPAC	No	PM's			
12241	6/29/2005	ECPAC	124000	5/20/2005		5/20/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Clean A/C enclosure			
12252	6/29/2005	ECPAC	124000	5/31/2005		5/31/2005	1	6	260.519989	0	260.519989	ECPAC	No	Cable pull			
12264	8/3/2005	ECPAC	124000	5/24/2005		5/24/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Work on sound transmission			
12268	8/3/2005	ECPAC	124000	5/2/2005		5/2/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Roof			
12269	8/3/2005	ECPAC	124000	5/3/2005		5/3/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Roof			

12270	8/3/2005	ECPAC	124000	5/3/2005		5/3/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Air handler #4 belt			
12286	8/3/2005	ECPAC	124000	5/16/2005		5/16/2005	1	5	217.0999908	0	217.0999908	ECPAC	No	Urinal			
12287	8/3/2005	ECPAC	124000	5/17/2005		5/17/2005	1	4	173.6799927	0	173.6799927	ECPAC	No	Urinal			
12291	8/3/2005	ECPAC	124000	5/18/2005		5/18/2005	1	4	173.6799927	0	173.6799927	ECPAC	No	Boiler pump seal			
12293	8/3/2005	ECPAC	124000	5/19/2005		5/19/2005	1	3	130.2599945	0	130.2599945	ECPAC	No	Boiler pump			
12295	8/3/2005	ECPAC	124000	5/20/2005		5/20/2005	1	4	173.6799927	0	173.6799927	ECPAC	No	Boiler pump			
12296	8/3/2005	ECPAC	124000	5/20/2005		5/20/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Sound transmission			
12297	8/3/2005	ECPAC	124000	5/23/2005		5/23/2005	1	4	173.6799927	0	173.6799927	ECPAC	No	Sound transmission			
12298	8/3/2005	ECPAC	124000	5/24/2005		5/24/2005	1	5	217.0999908	0	217.0999908	ECPAC	No	Sound transmission			
12302	8/3/2005	ECPAC	124000	5/25/2005		5/25/2005	1	7	303.9400024	0	303.9400024	ECPAC	No	Sound transmission			
12303	8/3/2005	ECPAC	124000	5/26/2005		5/26/2005	1	4	173.6799927	0	173.6799927	ECPAC	No	Sound transmission			
12389	8/15/2005	ECPAC	124000	6/21/2005		6/21/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Caster cups			
12406	8/15/2005	ECPAC	124000	6/2/2005		6/2/2005	1	4	173.6799927	0	173.6799927	ECPAC	No	Door lock			
12421	8/15/2005	ECPAC	124000	6/17/2005		6/17/2005	1	2	86.83999634	0	86.83999634	ECPAC	No	Chair caster cups			
12423	8/15/2005	ECPAC	124000	6/20/2005		6/20/2005	1	1	43.41999817	0	43.41999817	ECPAC	No	Chair caster cups			
12586	9/30/2005	ECPAC	241000	7/11/2005		7/11/2005	1	1	48.59999847	0	48.59999847	ECPAC	No	Lights			
12587	9/30/2005	ECPAC	241000	7/12/2005		7/12/2005	1	2	97.19999695	0	97.19999695	ECPAC	No	Lights			
12727	10/17/2005	ECPAC	241000	8/1/2005		8/1/2005	1	8	388.7999878	0	388.7999878	ECPAC	No	Wire pull			
12728	10/17/2005	ECPAC	241000	8/2/2005		8/2/2005	1	5	243	0	243	ECPAC	No	Wire pull			
12740	10/17/2005	ECPAC	241000	8/11/2005		8/11/2005	1	2	97.19999695	0	97.19999695	ECPAC	No	Broken outlet			
12757	10/17/2005	ECPAC	241000	8/1/2005		8/1/2005	1	8	388.7999878	0	388.7999878	ECPAC		Pull computer wire			
12758	10/17/2005	ECPAC	241000	8/2/2005		8/2/2005	1	5	243	0	243	ECPAC	No	Pull computer wire			
12772	11/7/2005	ECPAC	241000	8/24/2005		8/24/2005	1	2	97.19999695	0	97.19999695	ECPAC	No	Door closer			
12773	11/7/2005	ECPAC	241000	8/25/2005		8/25/2005	1	6	291.5999756	0	291.5999756	ECPAC	No	Door closer/door stops/eye hooks			
12820	11/15/2005	ECPAC	241000	9/27/2005		9/27/2005	1	4	194.3999939	0	194.3999939	ECPAC	No	A/C			
12891	2/3/2006	ECPAC	241000	9/20/2005		10/4/2005	15	1	48.59999847	0	48.59999847	ECPAC	No	faucet of sink next to wheelchair sink does not run water	Lee		
12902	2/3/2006	ECPAC	241000	9/26/2005		10/20/2005	25	6	291.5999756	65	356.5999756	ECPAC	No	has no flow			
12937	4/24/2006	ECPAC	241000	10/31/2005		10/31/2005	1	1	48.59999847	0	48.59999847	ECPAC	No	readjusted time clocks			
12950	4/24/2006	ECPAC	241000	10/6/2005		10/6/2005	1	2	97.19999695	0	97.19999695	ECPAC		A/C			
12951	4/24/2006	ECPAC	241000	10/7/2005		10/7/2005	1	2	97.19999695	0	97.19999695	ECPAC		Locks			
12954	4/24/2006	ECPAC	241000	10/17/2005		10/17/2005	1	3	145.7999878	0	145.7999878	ECPAC	No	A/C			
12955	4/24/2006	ECPAC	241000	10/18/2005		10/18/2005	1	8	388.7999878	0	388.7999878	ECPAC		A/C ECPAC			
12956	4/24/2006	ECPAC	241000	10/19/2005		10/19/2005	1	8	388.7999878	0	388.7999878	ECPAC		A/C			
12957	4/24/2006	ECPAC	241000	10/20/2005		10/20/2005	1	8	388.7999878	0	388.7999878	ECPAC	No	A/C			
12958	4/24/2006	ECPAC	241000	10/24/2005		10/24/2005	1	8	388.7999878	0	388.7999878	ECPAC	No	A/C			
12959	4/24/2006	ECPAC	241000	10/25/2005		10/25/2005	1	8	388.7999878	0	388.7999878	ECPAC	No	A/C			
12960	4/24/2006	ECPAC	241000	10/26/2005		10/26/2005	1	7	340.1999817	0	340.1999817	ECPAC		A/C			
12962	4/24/2006	ECPAC	241000	10/27/2005		10/27/2005	1	8	388.7999878	0	388.7999878	ECPAC		A/C			
12963	4/24/2006	ECPAC	241000	10/31/2005		10/31/2005	1	8	388.7999878	0	388.7999878	ECPAC	No	A/C			
12970	4/24/2006	ECPAC	241000	10/11/2005		10/11/2005	1	8	388.7999878	0	388.7999878	ECPAC	No	CLEAN ROOF ECPAC			
13019	4/25/2006	ECPAC	241000	10/26/2005		10/26/2005		5	243	0	243	ECPAC	No	A/C			
13020	4/25/2006	ECPAC	241000	10/27/2005		10/27/2005		8	388.7999878	0	388.7999878	ECPAC	No	A/C			
13021	4/25/2005	ECPAC	241000	10/28/2005		10/28/2005		8	388.7999878	0	388.7999878	ECPAC	No	A/C			

13107	4/28/2006	ECPAC	241000	11/1/2005	11/1/2005		8	388.7999878	0	388.7999878	ECPAC	No	A/C			
13108	4/28/2006	ECPAC	241000	11/2/2005	11/2/2005		8	388.7999878	0	388.7999878	ECPAC	No	A/C			
13109	4/28/2006	ECPAC	241000	11/3/2005	11/3/2005		7	340.1999817	0	340.1999817	ECPAC	No	A/C			
13111	4/28/2006	ECPAC	241000	11/4/2005	11/4/2005		4	194.3999939	0	194.3999939	ECPAC	No	A/C			
13118	4/26/2006	ECPAC	241000	11/14/2005	11/14/2005		3	145.7999878	0	145.7999878	ECPAC	No	TIME CLOCKS, STAR LIGHTS AT BACK DOOR			
13133	5/1/2006	ECPAC	241000	11/1/2005	11/1/2005		4	194.3999939	0	194.3999939	ECPAC	No	a/c at ecpac			
13135	5/1/2006	ECPAC	241000	11/2/2005	11/2/2005		4	194.3999939	0	194.3999939	ECPAC	No	a/c			
13148	5/1/2006	ECPAC	241000	11/16/2005	11/16/2005		2	97.19999695	0	97.19999695	ECPAC	No	tile			
13150	5/1/2006	ECPAC	241000	11/17/2005	11/17/2005		2	97.19999695	0	97.19999695	ECPAC	No	tile			
13152	5/1/2006	ECPAC	165000	11/21/2005	11/21/2005		4	194.3999939	0	194.3999939	ECPAC	No	stage light			
13153	5/1/2006	ECPAC	241000	11/22/2005	11/22/2005		4	194.3999939	0	194.3999939	ECPAC	No	stage light			
13158	5/1/2006	ECPAC	241000	11/30/2005	11/30/2005		1	48.59999847	0	48.59999847	ECPAC	No	ceiling hatch			
13176	5/1/2006	ECPAC	241000	11/21/2005	11/21/2005		2	97.19999695	0	97.19999695	ECPAC	No	troubleshoot orchestra lighting problem			
13177	5/1/2006	ECPAC	241000	11/22/2005	11/22/2005		5	243	0	243	ECPAC	No	continue orchestra lighting troubleshooting			
13219	5/2/2006	ECPAC	241000	12/7/2005	12/14/2005	8	2	97.19999695	0	97.19999695	ECPAC	No	Hang wreath		0372	
13251	5/2/2006	ECPAC	241000	12/19/2005	1/31/2006	44	3	145.7999878	0	145.7999878	ECPAC	No	light outside is out		0372	
13263	5/8/2006	ECPAC	241000	12/19/2005	2/2/2006	46	1	48.59999847	0	48.59999847	ECPAC	No	front door not closing right, poss. Leak through walls		0372	
13345	5/2/2006	ECPAC	241000	4/2/2006	4/14/2006	13	12	583.1999512	0	583.1999512	ECPAC	No	Repair HVAC	Melissa	0372	
13397	5/26/2006	ECPAC	241000	12/2/2005	12/2/2005	1	4	194.3999939	0	194.3999939	ECPAC	No	tested and researched replacement lighting relay for stage lights			
13403	5/26/2006	ECPAC	241000	12/6/2005	12/6/2005	1	5	243	0	243	ECPAC	No	replaced orchestral lighting relay			
13458	3/19/2007	ECPAC		3/29/2006	5/9/2006	42	1	48.59999847	0	48.59999847	ECPAC	No	DRINKING FOUNTAIN ON HOUSE LEFT NEAR BACKSTAGE ACCESS DOOR IN LOBBY IS MAKING A LOT OF NOISE AND SMELLS LIKE FUMES	STEEL	X0372	
13594	4/2/2007	ECPAC		3/29/2006	5/9/2006	42	1	48.59999847	0	48.59999847	ECPAC	No	drinking fountain on house left near backstage access door in lobby is making a lot of noise and smells like fumes	melina	x0372	
13635	9/11/2007	ECPAC	241000	7/2/2006	8/17/2006	47	6	291.5999756	0	291.5999756	ECPAC	No	all toilets are clogging more than usual and having problems flushing, is there way to shake them and apply more pressure.	mel	0372	
13992	1/31/2008	ECPAC	241000	9/27/2006	9/27/2006	1	4	194.3999939	17.28	211.6799927	n		Showers in second floor dressing rooms are not working-could be plumbing/pressure?	ECPAC	x0372	
14049	2/26/2008	ECPAC	241000	9/20/2007	10/8/2007	19	20	972	5	977	ECPAC	No	Water fountains in main lobby are putting out warm drinking water.	Melissa		

14061	2/27/2008	ECPAC	241000	9/20/2007	10/3/2007	14	1	48.59999847	0	48.59999847	ECPAC	No	First urinal in men's restroom leaked water out back when flushed.	Melissa	x0372
14062	2/27/2008	ECPAC	241000	9/28/2007	10/3/2007	6	1	48.59999847	0	48.59999847	ECPAC	No	One of men's fluorescent flickers - many complaints of causing dizziness - bulbs have been changed.	Melissa	x0372
14064	2/27/2008	ECPAC	241000	9/28/2007	10/1/2007	4	8	388.7999878	0	388.7999878	ECPAC	No	Doors to pit need to become unlockable from both sides because it is for fire doors that can't be propped open.	Patrick	x0343
14436	3/21/2008	ECPAC	241000	1/11/2008	2/8/2008	29	3	155.4300079	130	285.4299927	ECPAC	No	Door closure unit is broken off of door - fire door does not self close.	Patrick Hadlock	972-9602
14450	3/24/2008	ECPAC	241000	1/11/2008	2/4/2008	25	1	51.81000137	0	51.81000137	ECPAC	No	In the south stair well, third floor, and roof access the floor board molding needs to be repaired and re-adhered; trip hazard.	Patrick Hadlock	972-9602
14582	3/27/2008	ECPAC	241000	2/4/2008	2/4/2008	1	1	51.81000137	0	51.81000137	ECPAC	No	Mirrors in women's restrooms are off the walls (almost fell out).	R Bruggema	440-0372
14621	4/8/2008	ECPAC	241000	10/29/2007	11/15/2007	18	3	145.7999878	30	175.7999878	ECPAC	No	Third floor, south end fixture of fluorescent lighting not working.	Melissa	x0372
14622	4/10/2008	ECPAC	241000	10/29/2007	11/15/2007	18	2	97.19999695	10	107.1999969	ECPAC	No	Small restroom back stage with green light - fixture broken.	Melissa	x0372
14623	4/10/2008	ECPAC	241000	10/28/2007	11/15/2007	19	2	97.19999695	0	97.19999695	ECPAC	No	Third floor fire door won't close.	Melissa	x0372
14639	4/10/2008	ECPAC	241000	10/29/2007	11/7/2007	10	2	97.19999695	0	97.19999695	ECPAC	No	Back door not properly shutting from loading dock to back stage.	Melissa	x0372
14661	4/15/2008	ECPAC	241000	3/9/2008	3/24/2008	16	3	155.4300079	75	230.4300079	ECPAC	No	Faucet leaks, stays on, and drips. Last one on right, under tilt mirror.	R Bruggema	x0372
14710	5/9/2008	ECPAC	241000	3/28/2008	4/22/2008	26	2	103.6200027	0	103.6200027	ECPAC	No	Stage level dressing room/make-up room (most southern), door knob falling off	Rob Bruggema	x0372
14736	5/9/2008	ECPAC	241000	3/16/2008	4/9/2008	25	8	414.480011	0	414.480011	ECPAC	No	Front main entrance left hand door on east side slams closed, needs adjusting.	Rob Bruggema	x0372
14797	12/8/2008	ECPAC	241000	6/5/2008	7/1/2008	27	2	103.6200027	0	103.6200027	ECPAC	No	DOOR HANDLE FELL OFF STAR DRESSING ROOM DOOR ON STAGE LEVEL.	MELISSA HILL	X0372

14851	12/9/2008	ECPAC	241000	7/29/2008	8/4/2008	7	2	103.6200027	21	124.6200027	ECPAC	No	WALL SWITCH/TIMER WON'T STAY ON-WORN OUT. MEN'S SECOND FLOOR DRESSING ROOM EAST WALL STRAIGHT IN FROM DOOR	R BRUGGEM A	X0372
14882	12/16/2008	ECPAC	241000	8/10/2008	9/8/2008	30	3	155.4300079	0	155.4300079	ECPAC	No	TRACK LIGHTING IS NOT WORKING PROPERLY. TRIED REPLACING BULBS AND CLEANING TRACKS BUT SEVERAL LIGHTS OUT.	MELISSA HILL	X0372
14883	12/16/2008	ECPAC	241000	8/5/2008	9/8/2008	35	4	207.2400055	0	207.2400055	ECPAC	No	LAST FIVE TO SIX SEATS IN LAST ROW NEXT TO SOUND BOOTH ARE NOT SECURED TO FLOOR ANYMORE AND NEED TO BE SECURED.	MELISSA HILL	X0372
14931	12/18/2008	ECPAC	241000	10/22/2008	11/20/2008	30	4	207.2400055	50	257.2399902	ECPAC	No	BACK STAGE WATER FOUNTAIN DOES NOT DISPENSE WATER		X0343
14946	12/18/2008	ECPAC	241000		10/21/2008		1	51.81000137	0	51.81000137	ECPAC	No	TOILET SEAT BROKEN - PRESSURE NEEDS TO BE RAISED IF POSSIBLE ON ALL TOILETS	MELISSA HILL	X0372
14983	1/16/2009	ECPAC	241000	10/23/2008	11/14/2008	23	4	207.2400055	95	302.2399902	ECPAC	No	Lights out on camel run outside and outside east and west exit spots	Melissa	x0372
15003	1/23/2009	ECPAC	241000		11/12/2008		3	155.4300079	0	155.4300079	ECPAC	No	Fire door has been pulled away from bottom and tampered with so it automatically opens instead of staying closed as intended.	Melissa Hill	x0372
15211	4/28/2009	ECPAC	124000	2/23/2009	3/3/2009	9	2	103.6200027	0	103.6200027	ECPAC	No	WINDOW SCREEN CAME OFF LOBBY LEFT OVER EXIT DOORS. SCREEN ROLLED UP IN OPERATIONS OFFICE.	MELISSA	0372
15212	4/28/2009	ECPAC	124000	2/23/2009	3/3/2009	9	1	51.81000137	0	51.81000137	ECPAC	No	BLUE WIRING EXPOSED IN CEILING NEAR BOX OFFICE DOOR AND LIFT. CLIPPED AND ATACHED CABLE BACK INTO TRACK.	MELISSA	0372
15412	7/29/2009	ECPAC	124000	6/23/2009	7/10/2009	18	1	51.81000137	0	51.81000137	ECPAC	No	PLEASE REMOVE MONTGOMERY WARD BROWN/TAN UPRIGHT FREEZER. DISPOSED OF FREEZER AT WASTE MANAGEMENT RECYCLE CENTER.	M HILL	
TOTL						148	4	\$98,569.54	0	\$110,496.18					